



GRANT-KOHR'S RANCH NATIONAL HISTORIC SITE

FACILITY MANAGEMENT RECORDS

1967-2009(bulk dates: 1975-2009)

FINDING AID



RGN04
ACC GRKO-01376
CAT GRKO 17039

Prepared by
Heidi Buhr
7/8/2009
National Park Service
REVISED

TABLE OF CONTENTS

Copyright and Restrictions	ii
History	1
Scope and Content	2
Hierarchy	4
Series Descriptions	12
Container List.....	33

COPYRIGHT AND RESTRICTIONS

The copyright law of the United States (Title 17, United States Code) governs the making of photocopies or other reproductions of copyrighted materials. The various state privacy acts govern the use of materials that document private individuals, groups, and corporations.

Under certain conditions specified in the law, libraries and archives are authorized to furnish a reproduction if the document does not infringe the privacy rights of an individual, group, or corporation. These specified conditions of authorized use include:

- non-commercial and non-profit study, scholarship, or research, or teaching
- criticism, commentary, or news reporting
- as a NPS preservation or security copy
- as a research copy for deposit in another institution

If a user later uses a copy or reproduction for purposes in excess of "fair use," the user may be personally liable for copyright, privacy, or publicity infringement. This institution's permission to obtain a photographic, xerographic, digital, or other copy of a document doesn't indicate permission to publish, exhibit, perform, reproduce, sell, distribute, or prepare derivative works from this document without first obtaining permission from the copyright holder and from any private individual, group, or corporation shown or otherwise recorded.

Permission to publish, exhibit, perform, reproduce, prepare derivative works from, sell, or otherwise distribute the item must be obtained by the user separately in writing from the holder of the original copyright (or if the creator is dead from his/her heirs) as well as from any individual(s), groups, or corporations whose name, image, recorded words, or private information (e.g., employment information) may be reproduced in the source material. The holder of the original copyright isn't necessarily the National Park Service. The National Park Service is not legally liable for copyright, privacy, or publicity infringement when materials are wrongfully used after being provided to researchers for "fair use."

This institution reserves the right to refuse to accept a copying order if fulfillment of the order is judged in violation of copyright or federal or state privacy or publicity law.

HISTORY

What is now known as the Grant-Kohrs Ranch was founded in 1861 by pioneer trader John Grant. The Ranch was purchased in 1866 by Conrad Kohrs, who used it as his home and headquarters for what would become a four-state, ten-million acre open range cattle empire. The site was brought into the modern era of cattle ranching by Kohrs' grandson, Conrad Kohrs Warren, who sold it to the National Park Service in 1972. Congress authorized the purchase of the ranch structures and surrounding land to "provide an understanding of the frontier cattle era of the Nation's history...and to interpret the nationally-significant values thereof for the benefit and inspiration of present and future generations." The site's ninety three historic structures and 1,600 acres of cultural landscape continue to be maintained as a working ranch. The facility management/maintenance division records began with the creation of the Grant-Kohrs National Historic Site in 1972. Majority of the records for projects are dated after the initial purchase of the ranch. Mike McWright was the first chief of maintenance and set up the record keeping system. The maintenance division started with two permanent employees. Employees in the division peaked during the 1980's and have declined to three permanent staff in 1999. From October 1, 1987 until Fall of 1993 the Grant-Kohrs maintenance department was also in charge of maintenance at Big Hole Battlefield site, located just South of Grant-Kohrs. Up until 1990 the maintenance department was in charge of ranching, haying and irrigation at Grant-Kohrs, which is now under the Natural Resource Management. The department title was originally the Maintenance Division; the title now is Facility Management.

SCOPE AND CONTENT

FACILITY MANAGEMENT RECORDS 1967-2009 (bulk dates: 1975-2009)

CATALOG NUMBER GRKO 17039

VOLUME [Count]5.5 [Extent] [Type of Unit]LF

DESCRIPTION

The collection includes architectural drawings, blue prints, correspondence, forms, field notes, papers, reports, sketches, negatives, photographic prints, and slides relating to the maintenance and preservation of historic structures.

ORGANIZATION

[Organization]Organized into series based on historic structure and format of material; documentation, oversize, photographs, and negatives: Series 1 HS1; Series 2 HS2; Series 3 HS3; Series 4 HS4; Series 5 HS5; Series 6 HS6; Series 7 HS7; Series 8 HS8; Series 9 HS9; Series 10 HS10; Series 11 HS11; Series 12 HS12; Series 13 HS13; Series 14 HS14; Series 15 HS15; Series 16 HS16; Series 17 HS17; Series 18 HS18; Series 19 HS19; Series 20 HS20; Series 21 HS21; Series 22 HS22; Series 23 HS23; Series 24 HS24; Series 25 HS25; Series 26 HS26; Series 27 HS27; Series 28 HS28; Series 29 HS29; Series 30 HS30; Series 31 HS31; Series 32 HS32; Series 33 HS33; Series 34 HS34; Series 35 HS35; Series 36 HS36; Series 37 HS37; Series 38 HS38; Series 39 HS39; Series 40 HS40; Series 41 HS41; Series 42 HS42; Series 43 HS43; Series 44 HS44; Series 45 HS45; Series 46 HS46; Series 47 HS47; Series 48 HS48; Series 49 HS49; Series 50 HS50; Series 51 HS51; Series 52 HS52; Series 53 HS53; Series 54 HS54; Series 55 HS55; Series 56 HS56; Series 57 HS57; Series 58 HS58; Series 59 HS59; Series 60 HS60; Series 61 HS61; Series 62 HS62; Series 63 HS63; Series 64 HS64; Series 65 HS65; Series 66 HS66; Series 67 HS67; Series 68 HS68; Series 69 HS69; Series 70 HS70; Series 71 HS71; Series 72 HS72; Series 73 HS73; Series 74 HS74; Series 75 HS75; Series 76 HS76; Series 77 HS77; Series 78 HS78; Series 79 HS79; Series 80 HS80;

Series 81 HS81; Series 82 HS82; Series 83 HS83; Series 84 HS84; Series 85 HS85; Series 86 HS86; Series 87 HS87; Series 88 HS88; Series 89 HS89; Series 90 HS90; Series 91 HS91; Series 92 HS92; Series 93 HS93; Series 94; Series 95; Series 96; Series 97; Series 98; Series 99; Series 100; Series 101; Series 102; Series 103; Series 104; Series 105; Series 106; Series 107; Series 108; Series 109; Series 110; Series 111; Series 112; Series 113; Series 114; Series 115; Series 116; Series 117 [Arrangement]

PROVENANCE

This collection was created from the working files of facility management/maintenance division. The records originate with the creation of the Grant-Kohrs Historic Site in 1972. The creators of the records include Mike McWright, facility manager, Harrison Goodall, contract preservationist, and outside agencies such as architects that worked on projects for the facility management division. Some records were created by other departments in the NPS, but concern projects in the maintenance department. Summer, 1999 was the first time records were transferred from the facility management division to the archives, and a schedule is being developed to transfer records to the archives on a regular basis from this point on. Shadow files of the facility management division were created whereby all originals were photocopied, the originals were placed into the archives and the copies were placed into Mike McWright's working files. Some original photos and architectural drawings were kept in the working files. (Negatives are in the archives, and the architectural drawings will be duplicated onto non-acidic paper and placed into the archives).

RESTRICTIONS

NO

*ASSOCIATED
MATERIALS*

Grant-Kohrs Ranch National Historic Site Rodd L.
Wheaton, Historic Study Reports, Central Files, Dr.
Nicholas L. Scattish, Ranch House Window Project

HIERARCHY

1. PROJECTS RELATED TO HS1 RANCH HOUSE, 1973-2008
2. PROJECTS RELATED TO HS2 BUNKHOUSE ROW, 1974-2005
3. PROJECTS RELATED TO HS3 BLACKSMITH SHOP, 1972-2005
4. PROJECTS RELATED TO HS4 COAL SHED, 1981-2005
5. PROJECTS RELATED TO HS5 ICE HOUSE, 1974-2005
6. PROJECTS RELATED TO HS6 GRAINARY, 1975-2006
7. PROJECTS RELATED TO HS7 DRAFT HORSE BARN, 1975-2005
8. PROJECTS RELATED TO HS8 PRIVY, 1976-2005
9. PROJECTS RELATED TO HS9 DAIRY BARN, 1975-2008
10. PROJECTS RELATED TO HS10 OXEN BARN, 1978-2005
11. PROJECTS RELATED TO HS11 HORSE BARN (BIELENBERG BARN), 1975-2005
12. PROJECTS RELATED TO HS12 MACHINE SHED, 1978-2005
13. PROJECTS RELATED TO HS13 COW SHED, 1974-2005

14. PROJECTS RELATED TO HS14 STALLION BARN, 1975-2005
15. PROJECTS RELATED TO HS15 THOROUGHBRED BARN, 1975-2005
16. PROJECTS RELATED TO HS16 STALLION BARN (LEEDS-LION), 1976-2005
17. PROJECTS RELATED TO HS17 BUGGY SHED, 1976-2005
18. PROJECTS RELATED TO HS18 GRAINARY, 1975-2005
19. PROJECTS RELATED TO HS19 STALLION BARN, 1978-2008
20. PROJECTS RELATED TO HS20 PRIVY, 1975-2005
21. PROJECTS RELATED TO HS 21 BROODING HOUSE, 1976-2005
22. PROJECTS RELATED TO HS22 CHICKEN HOUSE, 1976-2005
23. PROJECTS RELATED TO HS23 GRAINARY, 1975-2005
24. PROJECTS RELATED TO HS24 STOCK SHELTER, 1981-2005
25. PROJECTS RELATED TO HS25 STOCK SHELTER, 1981-2005
26. PROJECTS RELATED TO HS26 HAY STORAGE, 1981-2005
27. PROJECTS RELATED TO HS27 STOCK SHELTER, 1980-2005
28. PROJECTS RELATED TO HS28 FEED STORAGE HOUSE, 1977-2005
29. PROJECTS RELATED TO HS29 STOCK SHELTER, 1980-2005

30. PROJECTS RELATED TO HS30 STALLION BARN, 1979-2008

31. PROJECTS RELATED TO HS31 FEED STORAGE HOUSE, 1977-2005

32. PROJECTS RELATED TO HS32 STOCK SHELTER, 1981-2005

33. PROJECTS RELATED TO HS33 STOCK SHELTER, 1981-2005

34. PROJECTS RELATED TO HS34 STORAGE SHED, 1978-2008

35. PROJECTS RELATED TO HS35 CATTLE SCALE, 1975-2008

36. PROJECTS RELATED TO HS36 FEED RACK, 1982-2005

37. PROJECTS RELATED TO HS37 FEED RACK, 1982-2005

38. PROJECTS RELATED TO HS38 FEED RACK, 1982-2005

39. PROJECTS RELATED TO HS39 MANURE PIT, 1975-2005

40. PROJECTS RELATED TO HS40 BEEF HOIST, 1982-2008

41. PROJECTS RELATED TO HS41 SQUEEZE CHUTE, 1976-2008

42. PROJECTS RELATED TO HS42 FEED RACK, 1975-2005

43. PROJECTS RELATED TO HS43 FEED RACK, 1982-2005

44. PROJECTS RELATED TO HS44 FEED RACK, 1982-2005

45. PROJECTS RELATED TO HS45 FEED BUNKER, 1978-2005
46. PROJECTS RELATED TO HS46 FEED BUNKER, 1978-2005
47. PROJECTS RELATED TO HS47 SQUEEZE CHUTE, 1982-2008
48. PROJECTS RELATED TO HS48 FEED BUNKER, 1982-2005
49. PROJECTS RELATED TO HS49 FEED BUNKER, 1981-2005
50. PROJECTS RELATED TO HS50 FLUME, ACTIVE, 1982-2005
51. PROJECTS RELATED TO HS51 FLUME, INACTIVE, 1976-2001
52. PROJECTS RELATED TO HS52 FEED BUNKER, 1976-2005
53. PROJECTS RELATED TO HS53 SQUEEZE CHUTE, 1976-2008
54. PROJECTS RELATED TO HS54 BRIDGE, 1994
55. PROJECTS RELATED TO HS55 BRIDGE, 1980-2005
56. PROJECTS RELATED TO HS56 RAILROAD, 1985-2005
57. PROJECTS RELATED TO HS57 SIPHON, 2005
58. PROJECTS RELATED TO HS58 WARREN HOUSE, 1994-2005
59. PROJECTS RELATED TO HS59 CHICKEN COOP, 1995-2008

60. PROJECTS RELATED TO HS60 BOAT HOUSE, 2001-2008

61. PROJECTS RELATED TO HS61 WARREN HOUSE GARAGE, 2001-2005

62. PROJECTS RELATED TO HS62 BARN, 1994-2005

63. PROJECTS RELATED TO HS63 BARN, 1994-2005

64. PROJECTS RELATED TO HS64 RED BARN, 1989-2005

65. PROJECTS RELATED TO HS65 METAL BARN, 1991-2005

66. PROJECTS RELATED TO HS66 SCALE HOUSE, 1980-2005

67. PROJECTS RELATED TO HS67 SQUEEZE CHUTE, 2005-2008

68. PROJECTS RELATED TO HS68 FEED RACK, 1990-2005

69. PROJECTS RELATED TO HS69 LOADING CHUTE, 1993-2005

70. PROJECTS RELATED TO HS70 COW SHED, 1980-2005

71. PROJECTS RELATED TO HS71 COW SHED, 1993-2005

72. PROJECTS RELATED TO HS72 COW SHED, 1993-2005

73. PROJECTS RELATED TO HS73 COW SHED, 1993-2005

74. PROJECTS RELATED TO HS74 COW SHED, 1993-2005

75. PROJECTS RELATED TO HS75 COW SHED, 1993-2005

76. PROJECTS RELATED TO HS76 COW SHED, 1993-2005
77. PROJECTS RELATED TO HS77 COW SHED, 1992-2005
78. PROJECTS RELATED TO HS78 FEED HOUSE, 2005
79. PROJECTS RELATED TO HS79 FEED HOUSE, 2005
80. PROJECTS RELATED TO HS80 FEED HOUSE, 2005
81. PROJECTS RELATED TO HS81 FEED HOUSE, 2005
82. PROJECTS RELATED TO HS82 FEED HOUSE, 2005
83. PROJECTS RELATED TO HS83 FEED HOUSE, 2005
84. PROJECTS RELATED TO HS84 FEED HOUSE, 2005
85. PROJECTS RELATED TO HS85 PUMP HOUSE, 1999-2005
86. PROJECTS RELATED TO HS86 PUMP HOUSE, 1990-2005
87. PROJECTS RELATED TO HS87 PUMP HOUSE, 1989-2005
88. PROJECTS RELATED TO HS88 PUMP HOUSE, 2000-2005
89. PROJECTS RELATED TO HS89 CLARK FORK RIVER BRIDGE, 1976-2008
90. PROJECTS RELATED TO HS90 SLEW BRIDGE, 1980-2008

91. PROJECTS RELATED TO HS91 WEST SIDE DITCH SYSTEM, 2005
92. PROJECTS RELATED TO HS92 KOHRS-MANNING DITCH SYSTEM, 2005
93. PROJECTS RELATED TO HS93 WARREN DITCH SYSTEM, 2005
94. SCOPE OF WORK RESTORATION OF HISTORIC STRUCTURES REVISED RECOMMENDATIONS DRAFT COPY 1980, 1980
95. SCOPE OF WORK RESTORATION: HS3 THRU HS31, Unknown
96. WARREN RANCH AREA SPECIFICATIONS 1990, 1990
97. GENERAL HISTORIC STRUCTURE SPECIFICATIONS, 1980-1995
98. HISTORIC PRESERVATION MAINTENANCE GUIDES 1979, 1979
99. GEOTECHNICAL INVESTIGATION AND EXPLORATORY BORINGS REPORTS 1979, 1979
100. PRESERVATION GUIDE TECHNICAL MANUAL MARCH 7, 1983, 1983
101. PRESERVATION GUIDE: INSTRUCTIONS AND FORMS, Unknown
102. DRAFT MAINTENANCE GUIDES JRM 78-19 JUNE 1, 1979 LOG STRUCTURES, 1979
103. DRAFT MAINTENANCE GUIDES JRM 78-19 JUNE 1, 1979 FRAME BUILDINGS, 1979
104. RANCH FENCING SYSTEM 1983-2009, 1983-2009

105. RANCH FENCING SYSTEM DUPLICATE PHOTOGRAPHS, 1995-2005
106. PARKING LOT PROJECTS 1983-2003, 1983-2003
107. SURFACE TREAT PARKING AREA CONTRACT #P1586010007 2001, 2001
108. ROAD INVENTORY AND NEEDS STUDY 1980, 1980
109. PARKING AREA, TRAIL, AND UTILITIES SPECIFICATIONS 1975, 1975
110. COTTONWOOD CREEK TRAIL, 1995
111. JOHNSON CREEK TRAIL, 1995
112. FLOODING/TRAIL UNDERPASS 1996, 1996
113. PHOTOGRAPH LOGS FOR NEGATIVES AND SLIDES, 1994-2005
114. PHOTOGRAPH INDEX CARDS, 2001-2004
115. OVERSIZE ARCHITECTURAL DRAWINGS, 1967-2005 (bulk dates: 1973-1986)
116. FACILITY MANAGEMENT HISTORIC STRUCTURE PROJECT NEGATIVES AND SLIDES
117. COMPACT DISKS OF PHOTOGRAPHS AND FLOPPY DISKS, 2001-2004

SERIES DESCRIPTIONS

1. PROJECTS RELATED TO HS1 RANCH HOUSE, 1973-2008

Organized into four sub-subseries: Sub-subseries 1 Garden; Sub-subseries 2 Roof Projects; Sub-subseries 3 Windows; Sub-subseries 4 Re-Painting.

This series is arranged by projects related to HS1 Ranch House, after being initially organized by Sub-subseries.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to all projects for HS1 Ranch House.

2. PROJECTS RELATED TO HS2 BUNKHOUSE ROW, 1974-2005

This series is arranged by projects related to HS2 Bunkhouse Row.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to all projects for HS2 Bunk House Row.

3. PROJECTS RELATED TO HS3 BLACKSMITH SHOP, 1972-2005

This series is arranged by documentation and photographic materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS3 Blacksmith Shop.

4. PROJECTS RELATED TO HS4 COAL SHED, 1981-2005

This series is arranged by documents and photographic materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversized materials, and photographs relating to projects for HS4 Coal Shed.

5. *PROJECTS RELATED TO HS5 ICE HOUSE, 1974-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversized materials, and photographs relating to all projects for HS5 Ice House.

6. *PROJECTS RELATED TO HS6 GRAINERY, 1975-2006*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversized materials, and photographs relating to projects for HS6 Grainary.

7. *PROJECTS RELATED TO HS7 DRAFT HORSE BARN, 1975-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS7 Draft Horse Barn.

8. *PROJECTS RELATED TO HS8 PRIVY, 1976-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversized materials, and photographs relating to projects for HS8 Privy.

9. *PROJECTS RELATED TO HS9 DAIRY BARN, 1975-2008*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversized materials, and photographs relating to projects for HS9 Dairy Barn.

10. *PROJECTS RELATED TO HS10 OXEN BARN, 1978-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS10 Oxen Barn.

11. *PROJECTS RELATED TO HS11 HORSE BARN (BIELENBERG BARN), 1975-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS11 Horse Barn (Bielenberg Barn).

12. *PROJECTS RELATED TO HS12 MACHINE SHED, 1978-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS12 Machine Shed.

13. *PROJECTS RELATED TO HS13 COW SHED, 1974-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS13 Cow Shed.

14. *PROJECTS RELATED TO HS14 STALLION BARN, 1975-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS14 Stallion Barn.

15. *PROJECTS RELATED TO HS15 THOROUGHBRED BARN, 1975-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversized materials, and photographs relating to projects for HS15 Thoroughbred Barn.

16. *PROJECTS RELATED TO HS16 STALLION BARN (LEEDS-LION), 1976-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS16 Stallion Barn (Leeds-Lion).

17. *PROJECTS RELATED TO HS17 BUGGY SHED, 1976-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversized materials, and photographs relating to projects for HS17 Buggy Shed.

18. *PROJECTS RELATED TO HS18 GRAINARY, 1975-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversized materials, and photographs relating to projects for HS18 Grainary.

19. *PROJECTS RELATED TO HS19 STALLION BARN, 1978-2008*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS19 Stallion Barn.

20. *PROJECTS RELATED TO HS20 PRIVY, 1975-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS20 Privy.

21. *PROJECTS RELATED TO HS 21 BROODING HOUSE, 1976-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS21 Brooding House.

22. *PROJECTS RELATED TO HS22 CHICKEN HOUSE, 1976-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS22 Chicken House.

23. *PROJECTS RELATED TO HS23 GRAINARY, 1975-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversized materials, and photographs relating to projects for HS23 Grainary.

24. *PROJECTS RELATED TO HS24 STOCK SHELTER, 1981-2005*

This series is arranged by documentation of projects related to HS24 Stock Shelter.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS24 Stock Shelter.

25. *PROJECTS RELATED TO HS25 STOCK SHELTER, 1981-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS25 Stock Shelter.

26. *PROJECTS RELATED TO HS26 HAY STORAGE, 1981-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS26 Hay Storage.

27. PROJECTS RELATED TO HS27 STOCK SHELTER, 1980-2005

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS27 Stock Shelter.

28. PROJECTS RELATED TO HS28 FEED STORAGE HOUSE, 1977-2005

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS28 Feed Storage House.

29. PROJECTS RELATED TO HS29 STOCK SHELTER, 1980-2005

This series is arranged by documentation of projects related to HS29 Stock Shelter.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS29 Stock Shelter.

30. PROJECTS RELATED TO HS30 STALLION BARN, 1979-2008

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS30 Stallion Barn.

31. PROJECTS RELATED TO HS31 FEED STORAGE HOUSE, 1977-2005

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS31 Feed Storage House.

32. *PROJECTS RELATED TO HS32 STOCK SHELTER, 1981-2005*

This series is arranged by documentation of projects related to HS32 Stock Shelter.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS32 Stock Shelter.

33. *PROJECTS RELATED TO HS33 STOCK SHELTER, 1981-2005*

This series is arranged by documentation of projects related to HS33 Stock Shelter.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS33 Stock Shelter.

34. *PROJECTS RELATED TO HS34 STORAGE SHED, 1978-2008*

This series is arranged by documentation of projects related to HS34 Storage Shed.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS34 Storage Shed.

35. *PROJECTS RELATED TO HS35 CATTLE SCALE, 1975-2008*

This series is arranged by documentation of projects for HS35 Cattle Scale.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS35 Cattle Scale.

36. *PROJECTS RELATED TO HS36 FEED RACK, 1982-2005*

This series is arranged by documentation of projects related to HS36 Feed Rack.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS36 Feed Rack.

37. *PROJECTS RELATED TO HS37 FEED RACK, 1982-2005*

This series is arranged by documentation of projects for HS37 Feed Rack.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS37 Feed Rack.

38. *PROJECTS RELATED TO HS38 FEED RACK, 1982-2005*

This series is arranged by documentation of projects for HS38 Feed Rack.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS38 Feed Rack.

39. *PROJECTS RELATED TO HS39 MANURE PIT, 1975-2005*

This series is arranged by documentation of projects for HS39 Manure Pit.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS39 Manure Pit.

40. *PROJECTS RELATED TO HS40 BEEF HOIST, 1982-2008*

This series is arranged by documentation of projects for HS40 Beef Hoist.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS40 Beef Hoist.

41. *PROJECTS RELATED TO HS41 SQUEEZE CHUTE, 1976-2008*

This series is arranged by documentation of projects for HS41 Squeeze Chute.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS41 Squeeze Chute.

42. *PROJECTS RELATED TO HS42 FEED RACK, 1975-2005*

This series is arranged by documentation of projects for HS42 Feed Rack.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS42 Feed Rack.

43. *PROJECTS RELATED TO HS43 FEED RACK, 1982-2005*

This series is arranged by documentation of projects for HS43 Feed Rack.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS43 Feed Rack.

44. *PROJECTS RELATED TO HS44 FEED RACK, 1982-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, photographs, and architectural data relating to projects for HS44 Feed Rack.

45. *PROJECTS RELATED TO HS45 FEED BUNKER, 1978-2005*

This series is arranged by documentation of projects for HS45 Feed Bunker.

Correspondence, forms, architectural drawings, work request logs, architectural data, and oversize materials relating to projects for HS45 Feed Bunker.

46. *PROJECTS RELATED TO HS46 FEED BUNKER, 1978-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversize materials, and photographs relating to projects for HS46 Feed Bunker.

47. *PROJECTS RELATED TO HS47 SQUEEZE CHUTE, 1982-2008*

This series is arranged by documentation of projects for HS47 Squeeze Chute.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS47 Squeeze Chute.

48. *PROJECTS RELATED TO HS48 FEED BUNKER, 1982-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data and photographs relating to projects for HS48 Feed Bunker.

49. *PROJECTS RELATED TO HS49 FEED BUNKER, 1981-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS49 Feed Bunker.

50. *PROJECTS RELATED TO HS50 FLUME, ACTIVE, 1982-2005*

This series is arranged by documentation of projects related to HS50 Flume, Active.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS50 Flume, Active.

51. *PROJECTS RELATED TO HS51 FLUME, INACTIVE, 1976-2001*

This series is arranged by documentation of projects related to HS51 Flume, Inactive.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS51 Flume, Inactive.

52. *PROJECTS RELATED TO HS52 FEED BUNKER, 1976-2005*

This series is arranged by documentation of projects for HS52 Feed Bunker.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS52 Feed Bunker.

53. *PROJECTS RELATED TO HS53 SQUEEZE CHUTE, 1976-2008*

This series is arranged by documentation of projects related to HS53 Squeeze Chute.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS53 Squeeze Chute.

54. *PROJECTS RELATED TO HS54 BRIDGE, 1994*

This series is arranged by documentation of projects related to HS54 Bridge.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS54 Bridge.

55. *PROJECTS RELATED TO HS55 BRIDGE, 1980-2005*

This series is arranged by documentation of projects related to HS55 Bridge.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS55 Bridge.

56. *PROJECTS RELATED TO HS56 RAILROAD, 1985-2005*

This series is arranged by documentation of projects for HS56 Railroad.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS56 Railroad.

57. *PROJECTS RELATED TO HS57 SIPHON, 2005*

This series is arranged by documentation of projects for HS57 Siphon.

National Historic House Specifications

58. *PROJECTS RELATED TO HS58 WARREN HOUSE, 1994-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversize materials, and photographs relating to projects for HS58 Warren House.

59. *PROJECTS RELATED TO HS59 CHICKEN COOP, 1995-2008*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversize materials, and photographs relating to projects for HS59 Chicken Coop.

60. *PROJECTS RELATED TO HS60 BOAT HOUSE, 2001-2008*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS60 Boat House.

61. *PROJECTS RELATED TO HS61 WARREN HOUSE GARAGE, 2001-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS61 Warren House Garage.

62. *PROJECTS RELATED TO HS62 BARN, 1994-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS62 Barn.

63. *PROJECTS RELATED TO HS63 BARN, 1994-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS63 Barn.

64. *PROJECTS RELATED TO HS64 RED BARN, 1989-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS64 Red Barn.

65. *PROJECTS RELATED TO HS65 METAL BARN, 1991-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS65 Metal Barn.

66. *PROJECTS RELATED TO HS66 SCALE HOUSE, 1980-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS66 Scale House.

67. PROJECTS RELATED TO HS67 SQUEEZE CHUTE, 2005-2008

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS67 Squeeze Chute.

68. PROJECTS RELATED TO HS68 FEED RACK, 1990-2005

This series is arranged by documentation of projects for HS68 Feed Rack.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS68 Feed Rack.

69. PROJECTS RELATED TO HS69 LOADING CHUTE, 1993-2005

This series is arranged by documentation of projects for HS69 Loading Chute.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS69 Loading Chute.

70. PROJECTS RELATED TO HS70 COW SHED, 1980-2005

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS70 Cow Shed.

71. PROJECTS RELATED TO HS71 COW SHED, 1993-2005

This series is arranged by documentation of projects for HS71 Cow Shed.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS71 Cow Shed.

72. PROJECTS RELATED TO HS72 COW SHED, 1993-2005

This series is arranged by documentation of projects for HS72 Cow Shed.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS72 Cow Shed.

73. PROJECTS RELATED TO HS73 COW SHED, 1993-2005

This series is arranged by documentation of projects for HS73 Cow Shed.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS73 Cow Shed.

74. PROJECTS RELATED TO HS74 COW SHED, 1993-2005

This series is arranged by documentation of projects for HS74 Cow Shed.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS74 Cow Shed.

75. PROJECTS RELATED TO HS75 COW SHED, 1993-2005

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS75 Cow Shed.

76. PROJECTS RELATED TO HS76 COW SHED, 1993-2005

This series is arranged by documentation of projects for HS76 Cow Shed.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS76 Cow Shed.

77. PROJECTS RELATED TO HS77 COW SHED, 1992-2005

This series is arranged by documentation of projects for HS77 Cow Shed.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS77 Cow Shed.

78. *PROJECTS RELATED TO HS78 FEED HOUSE, 2005*

This series is arranged by documentation of projects for HS78 Feed House.

National Historic House Specifications

79. *PROJECTS RELATED TO HS79 FEED HOUSE, 2005*

This series is arranged by documentation related to HS79 Feed House.

National Historic House Specifications

80. *PROJECTS RELATED TO HS80 FEED HOUSE, 2005*

This series is arranged by documentation of projects for HS80 Feed House.

National Historic House Specifications

81. *PROJECTS RELATED TO HS81 FEED HOUSE, 2005*

This series is arranged by documentation of projects for HS81 Feed House.

National Historic House Specifications

82. *PROJECTS RELATED TO HS82 FEED HOUSE, 2005*

This series is arranged by documentation of projects for HS82 Feed House.

National Historic House Specifications

83. *PROJECTS RELATED TO HS83 FEED HOUSE, 2005*

This series is arranged by documentation of projects for HS83 Feed House.

National Historic House Specifications

84. *PROJECTS RELATED TO HS84 FEED HOUSE, 2005*

This series is arranged by documentation of projects for HS84 Feed House.

National Historic House Specifications

85. *PROJECTS RELATED TO HS85 PUMP HOUSE, 1999-2005*

This series is arranged by documentation of projects for HS85 Pump House.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS85 Pump House.

86. *PROJECTS RELATED TO HS86 PUMP HOUSE, 1990-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS86 Pump House.

87. *PROJECTS RELATED TO HS87 PUMP HOUSE, 1989-2005*

This series is arranged by documentation of projects for HS87 Pump House.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for HS87 Pump House.

88. *PROJECTS RELATED TO HS88 PUMP HOUSE, 2000-2005*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, and photographs relating to projects for HS88 Pump House.

89. *PROJECTS RELATED TO HS89 CLARK FORK RIVER BRIDGE, 1976-2008*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversize materials, and photographs relating to projects for HS89 Clark Fork River Bridge.

90. *PROJECTS RELATED TO HS90 SLEW BRIDGE, 1980-2008*

This series is arranged by documentation and photograph materials.

Correspondence, forms, architectural drawings, work request logs, architectural data, oversized materials, and photographs relating to projects for HS90 Slew Bridge.

91. *PROJECTS RELATED TO HS91 WEST SIDE DITCH SYSTEM, 2005*

This series is arranged by documentation of projects for HS91 West Side Ditch System.

National Historic House Specifications

92. *PROJECTS RELATED TO HS92 KOHRS-MANNING DITCH SYSTEM, 2005*

This series is arranged by documentation of projects for HS92 Kohrs-Manning Ditch System.

National Historic House Specifications

93. *PROJECTS RELATED TO HS93 WARREN DITCH SYSTEM, 2005*

This series is arranged by documentation of projects for HS93 Warren Ditch System.

National Historic House Specifications

94. *SCOPE OF WORK RESTORATION OF HISTORIC STRUCTURES REVISED RECOMMENDATIONS DRAFT COPY 1980, 1980*

This series is arranged by documentation for Scope of Work Restoration of Historic Structures Revised Recommendations Draft Copy 1980.

Scope of Work Restoration of Historic Structures Revised Recommendations Draft Copy 1980

95. *SCOPE OF WORK RESTORATION: HS3 THRU HS31, Unknown*

This series is arranged by documentation related to Scope of Work Restoration: HS3 thru HS31.

Scope of Work Restoration: HS3 thru HS31 Guides

96. *WARREN RANCH AREA SPECIFICATIONS 1990, 1990*

This series is arranged by documentation related to Warren Ranch Area Specifications 1990.

Warren Ranch Area Specifications 1990

97. *GENERAL HISTORIC STRUCTURE SPECIFICATIONS, 1980-1995*

This series is arranged by documentation related to General Historic Structure Specifications.

General Historic Structure Specifications

98. *HISTORIC PRESERVATION MAINTENANCE GUIDES 1979, 1979*

This series is arranged by documentation related to Historic Preservation Maintenance Guides 1979.

Historic Preservation Maintenance Guides 1979

99. *GEOTECHNICAL INVESTIGATION AND EXPLORATORY BORINGS REPORTS 1979, 1979*

This series is arranged by documentation related to Geotechnical Investigation and Exploratory Borings Reports 1979.

Correspondence, Exploratory Borings Proposed Water Service Line written by Chen and Associates, Inc. 1979, and Geotechnical Investigation written by Chen and Associates, Inc. 1979

100. *PRESERVATION GUIDE TECHNICAL MANUAL MARCH 7, 1983, 1983*

This series is arranged by documentation of the Preservation Guide Technical Manual March 7, 1983.

Preservation Guide Technical Manual March 7, 1983

101. *PRESERVATION GUIDE: INSTRUCTIONS AND FORMS, Unknown*

This series is arranged by documentation of the Preservation Guide: Instructions and Forms.

Preservation Guide: Instructions and Forms

102. *DRAFT MAINTENANCE GUIDES JRM 78-19 JUNE 1, 1979 LOG STRUCTURES, 1979*

This series is arranged by documentation of the Draft Maintenance Guides JRM 78-19 June1, 1979 Log Structures by structure.

Draft Maintenance Guides JRM 78-19 June1, 1979 Log Structures

103. *DRAFT MAINTENANCE GUIDES JRM 78-19 JUNE 1, 1979 FRAME BUILDINGS, 1979*

This series is arranged by documentation for Draft Maintenance Guides JRM 78-19 June 1, 1979 Frame Buildings.

Elements of Structures in Non-Maintenance State List HS2-HS31
Maintenance Specifications Outline for Frame Buildings HS2 (Eastend), 3, 4, 6, 8, 9, 17, 18, 21, 22, 30, 31

104. *RANCH FENCING SYSTEM 1983-2009, 1983-2009*

This series is arranged by documentation related to the Ranch Fencing System.

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for Ranch Fencing System.

105. *RANCH FENCING SYSTEM DUPLICATE PHOTOGRAPHS, 1995-2005*

This series is arranged chronologically.

Gate Repair 1995 Duplicate Photographs

Temporary Wind Break Near Feed Lots 2000 Duplicate Photograph

Gate Repair on Gate Near HS59 Before Repair 2005 Duplicate Photograph

106. *PARKING LOT PROJECTS 1983-2003, 1983-2003*

This series is arranged by documentation related to Parking Lot Projects

Correspondence, forms, architectural drawings, work request logs, and architectural data relating to projects for Parking Lot Projects.

107. *SURFACE TREAT PARKING AREA CONTRACT #P1586010007 2001, 2001*

This series is arranged by documentation related to the Surface Treat Parking Area Contract.

Correspondence, forms, architectural drawings, architectural data, and contract forms related to the Surface Treat Parking Area Project.

108. *ROAD INVENTORY AND NEEDS STUDY 1980, 1980*

This series is arranged by documentation related to the Road Inventory and Needs Study Booklet.

Forms related to the Road Inventory and Needs Study conducted for the Grant-Kohrs Ranch National Historic Site in 1980.

109. *PARKING AREA, TRAIL, AND UTILITIES SPECIFICATIONS 1975, 1975*

This series is arranged by documentation of Parking Area, Trail, and Utilities Specifications Booklet.

Grant-Kohrs Ranch National Historic Site Parking Area, Trail, and Utilities Specifications Project No. 1586-0582 May 27, 1975 Booklet.

110. *COTTONWOOD CREEK TRAIL, 1995*

This series is arranged by documentation of projects related to the Cottonwood Creek Trail.

Correspondence, work request logs, forms, Cottonwood Creek Trail Booklet, and architectural drawings related to the Cottonwood Creek Trail.

111. *JOHNSON CREEK TRAIL, 1995*

This series is arranged chronologically.

Correspondence related to projects for Johnson Creek Trail.

112. *FLOODING/TRAIL UNDERPASS 1996, 1996*

This series is arranged chronologically.

Architectural Drawing of flooding occurring on the ranch February 8-9, 1996.

113. *PHOTOGRAPH LOGS FOR NEGATIVES AND SLIDES, 1994-2005*

This series is arranged chronologically first by negative logs then chronologically by slide logs.

Photograph Logs for Negatives and Slides for Facility Management Records.

114. *PHOTOGRAPH INDEX CARDS, 2001-2004*

This series is arranged chronologically.

Photograph Index Cards related to the Facility Management Records Photographs and Negatives.

115. *OVERSIZE ARCHITECTURAL DRAWINGS, 1967-2005 (bulk dates: 1973-1986)*

This series is arranged by Historic Structure with HS1 Ranch House first, HS2 Bunkhouse Row second, and followed by folders containing all other Historic Structures documentation.

Newspapers, blueprints, photographs, maps, Mylar blueprints, and architectural drawings related to the Historical Structures on the Grant-Kohrs Ranch for the Facility Management Records.

116. FACILITY MANAGEMENT HISTORIC STRUCTURE PROJECT NEGATIVES AND SLIDES

This series is arranged chronologically first negatives then slides.

Negatives and slides related to projects for Facility Management Records.

117. COMPACT DISKS OF PHOTOGRAPHS AND FLOPPY DISKS, 2001-2004

This series is arranged chronologically by compact disks first and floppy disks second.

Compact disks and floppy disks for projects related to Facility Management Division.

Container List

Box 1

Series 001 *PROJECTS RELATED TO HSI RANCH HOUSE, 1973-2008*

Folder 001. HSI [Cultural Inventory Study Landscape: Modified Pathways 1997], 3/1/1997

This folder contains:

SUB-SUBSERIES Garden

Correspondence

Assessment of Actions Forms

Architectural drawings and photograph copies

Folder 002. HSI [Brick Walkway Duplicate Photographs], circa 2003

This folder contains:

SUB-SUBSERIES Garden

Color and Black and White photographs of the brick walkway installation

Folder 003. HSI [Plant Trees and Install Underground Sprinkler System 2001], 2001

This folder contains:

SUB-SUBSERIES

Garden

Correspondence

Landscaping and Irrigation Operation and Maintenance Manual

Compliance Review Form

Daily Diaries

Contract

Folder 004. HSI [Plant Trees and Install Underground Sprinkler System 2001 Duplicate Photographs], 2001

This folder contains:

SUB-SUBSERIES Garden

Existing Conditions for HSI Yard Photographs

New Cottonwood Trees Photographs

Connections in Basement for Irrigation System Photographs

Folder 005. HSI [Reconstruct Historic Picket Fence 2001], 2001

This folder contains:

SUB-SUBSERIES Garden

Correspondence

Compliance Review Form

Materials estimate form for fence reconstruction

Folder 006. HS1 [Reconstruct Historic Picket Fence 2001 Duplicate Photographs], 2001-2003

This folder contains:

SUB-SUBSERIES Garden

Duplicate photographs of HS1 garden and picket fence 2001-2003

Folder 007. HS1 [Walkway and Garden Edge Restoration 2008], 2008

This folder contains:

SUB-SUBSERIES Garden

Walkway and Garden Edge Restoration Project Description 2008

Folder 008. HS1 [Ranch House General Garden Restoration Projects], 1984-1988

This folder contains:

SUB-SUBSERIES Garden

Assessment of Effect forms

Work Order Log for garden restoration

Garden photograph copies

Folder 009. HS1 [General Garden Restoration Projects Duplicate Photographs], 2005

This folder contains:

SUB-SUBSERIES Garden

Duplicate photographs of the restoration of the bank in HS1 Garden 2005

Folder 010. HS1 [Analysis of Roof Metal 1998], 1988

This folder contains:

SUB-SUBSERIES Roof Projects

Correspondence

Metal roof chemical test results

Folder 011. HS1 [Reroofing Project 1997-1998], 1997-1998

This folder contains:

SUB-SUBSERIES Roof Projects

Work Order Logs for HS1 roof projects

Correspondence

Completion Report

Compliance Review Form

Folder 012. HS1 [Reroofing Project 1997-1998 Duplicate Photographs], 1998-1999

This folder contains:

SUB-SUBSERIES Roof Projects

Duplicate Photographs of HS1 Reroofing Projects 1998-1999

Folder 013. HS1 [Southwest Porch Reroof Projects 1983, 2005], 1983, 2005

This folder contains:

SUB-SUBSERIES Roof Projects

Correspondence

Architectural Drawings and Photograph Copies of Suggested Metal Ridge Capsection for HS1 Roof

Compliance Review Forms

PMIS Forms

Folder 014. HS1 [Historic Roofing Materials and Specifications 1998], 1998

This folder contains:

SUB-SUBSERIES Roof Projects

Historic Roofing Materials and Specifications Report

Folder 015. HS1 [Ranch House Reroofing Projects Duplicate Photographs], circa 1990

This folder contains:

SUB-SUBSERIES Roof Projects

Replacement of roof to Northern basement entrance duplicate photographs

Ranch House before roof work duplicate photographs

Folder 016. HS1 [Condition of Windows Report 1974], 1974

This folder contains:

SUB-SUBSERIES Windows

Condition of windows report 1974

Folder 017. HS1 [Windows and Screen Door Replacement 1992], 1992

This folder contains:

SUB-SUBSERIES Windows

Wood conservation research materials

Requisition Forms

Correspondence

Assessment of Effect Forms

Architectural Drawings

Folder 018. HS1 [South Bay Window (Room 113A) Re-Sash Project 1994], 1994

This folder contains:

SUB-SUBSERIES Windows

HS1 South Bay Window Room 113A Project Description List

Folder 019. HS1 [Windows and Screen Door Replacement 1995], 1995

This folder contains:

SUB-SUBSERIES Windows
Assessment of Effect Forms
Architectural Drawings
Scope of Work Forms
Project Photograph Lists

Folder 020. HS1 [Windows and Screen Door Replacement 1995 Duplicate Photographs], 1995

This folder contains:

SUB-SUBSERIES Windows
Window and Screen Door Repair Duplicate Photographs

Folder 021. HS1 [Paint Samples and Data 1984], 1984-1988

This folder contains:

SUB-SUBSERIES Re-Painting
Paint Samples and Data List for HS1 Windows
Paint to be used on HS1 Labels

Folder 022. HS1 [Ranch House Lead Abatement, Repair, and Repaint 2001], 2001

This folder contains:

SUB-SUBSERIES Re-Painting
Ranch House Lead Abatement, Repair, and Repaint Project Information FY 2001

Folder 023. HS1 [Ranch House Lead Abatement, Repair, and Repaint 2001 Duplicate Photographs], 2001

This folder contains:

SUB-SUBSERIES RepaintingHS1 Painting Project Duplicate Photographs 2001

Folder 024. HS1 [Interior and Exterior Work on Ranch House 1983-1988], 1983-1988

This folder contains:

Correspondence
Amendment of Solicitation/Modification of Contract
Architectural Drawings and Photograph copies
Lead Paint Test Reports

Folder 025. HS1 [Renovation of Mechanical and Electrical Systems 1983-1985], 1983-1985

This folder contains:

Lump Sum Contracts
Weekly Field Reports

Architectural Drawings and Photograph Copies
Renovation of Mechanical and Electrical Systems Completion Report

Folder 026. HS1 [Repointing HS1 Brick 1996], 1996

This folder contains:
Compliance Review Form
Assessment of Actions Forms

Folder 027. HS1 [UV Control in Ranch House], Unknown

This folder contains:
UV Control for HS1 Project Goals

Folder 028. HS1 [Graining, Regraining, and Inpainting 1995], 1995

This folder contains:
Scope of Work for Graining, Regraining, and Inpainting Project
Proposed Project Form

Folder 029. HS1 [Remove and Replace Attic Insulation 1990], 1990

This folder contains:
Completion Report
Requisition Forms
Commitment Control Register

Folder 030. HS1 [Front Porch Stabilization 1994-1995, 2003], 1994-2003

This folder contains:
Scope of Work for Front Porch Deck
Correspondence
PMIS Forms
Compliance Review Forms
Project Material Lists
Architectural Drawings

Folder 031. HS1 [Front Porch Stabilization 1994-1995, 2003 Duplicate Photographs], 2003

This folder contains:
HS1 Front Porch Duplicate Photographs 2003

Folder 032. HS1 [Southwest Porch Restoration Duplicate Photographs], 2005

This folder contains:
Southwest Porch Restoration Duplicate Photographs 2005

Folder 033. HS1 [Treat Wooden Features 1983], 1983-2004

This folder contains:
Correspondence
Completion Report Forms

Treat Wooden Features Materials List
Treat Wooden Features Narrative Statement

Folder 034. HS1 [Treat and Relocate Museum Objects 1983-1984], 1983-1984

This folder contains:
Treat and Relocate Museum Objects Completion Report

Folder 035. HS1 [Load Capacity of Second Floor 1984], 1984

This folder contains:
Correspondence
Overall Analysis Assumptions for HS1

Folder 036. HS1 [Construction Documents for Restoration Projects within HS1 and Rooms 106, 107, and 113], 1999-2001

This folder contains:
Construction documents including all working drawings and specifications for restoration projects within historic structure no. 1

Folder 037. HS1 [Architectural Data and Drawings], Unknown

This folder contains:
Architectural Data and Drawings

Folder 038. HS1 [Maintenance Inspection Forms 1982-1987], 1982-1987

This folder contains:
Maintenance Inspection Forms 1982-1987

Folder 039. HS1 [National Historic House Specifications 2005], 2005

This folder contains:
National Historic House Specifications 2005

Folder 040. HS1 [Work Request Logs 1973-1994], 1973-1994

This folder contains:
Work Request Logs
Architectural Photograph Copy

Folder 041. HS1 [Research Materials for HS1 Projects 1975-1985], 1975-1985

This folder contains:
Research Materials for HS1 Projects
Architectural Drawings
Con Warren Interviews
Correspondence

Folder 042. HS1 [Oversize Archive Separation Sheets], 5/28/2009

This folder contains:

Archives and Manuscript Collections Separation Sheets

Series 002 *PROJECTS RELATED TO HS2 BUNKHOUSE ROW, 1974-2005*

Folder 001. HS2 [Stabilize Support Posts on HS2 1982-2004], 1982-2004

This folder contains:

Correspondence

PMIS forms

Compliance Review Forms

Assessment of Effect Forms

Architectural Drawings

Folder 002. HS2 [Stabilize Support Posts 1982-2004 Duplicate Photographs], 1982-2004

This folder contains:

Stabilize Support Posts in HS2 Duplicate Photographs

Folder 003. HS2 [Replace Existing Barriers with Larger Barriers 1986], 1986

This folder contains:

Assessment of Effect Forms

General Specifications of Materials for HS2

Correspondence

Architectural Drawings

Folder 004. HS2 [Re-Roof and Install Electrical/ Fire Detection Conduit 1983], 1982

This folder contains:

Assessment of Effect Forms

Completion Report Forms

Existing Roof Specifications

Architectural Drawings and Photograph Copies

Folder 005. HS2 [Repainting and Whitewashing HS2 Projects 1983-1997], 1983-1997

This folder contains:

Assessment of Actions Forms

Scope of Work for Repainting and Whitewashing of HS2

Architectural Drawings and Photograph Copies

Whitewashing Formula

PMIS Forms

Completion Report Forms

Correspondence

Material Safety Data Sheet

**Folder 006. HS2 [Miscellaneous Repair Projects for HS2 1997-2003],
1997-2003**

This folder contains:

Compliance Review Forms
Scope of Work to Repair Damaged Stone Work on HS2
Architectural Drawings
PMIS Forms

**Folder 007. HS2 [Miscellaneous Repair Projects Duplicate Photographs],
2001**

This folder contains:

Damage to Northwest Corner Duplicate Photographs

Folder 008. HS2 [Maintenance Inspection Logs 1982-1987], 1982-1987

This folder contains:

Historic Structure Preservation Guide Forms 1982-1987

Folder 009. HS2 [Work Request Logs 1975-1993], 1975-1993

This folder contains:

Work Request Logs 1975-1993

Folder 010. HS2 [National Historic House Specifications 2005], 2005

This folder contains:

National Historic House Specifications 2005

Folder 011. HS2 [Architectural Data and Drawings], Unknown

This folder contains:

Architectural Data and Drawings for HS2

Folder 012. HS2 [Research Materials for HS2 1974-1993], 1974-1993

This folder contains:

Interview Transcript with Earl F. Allen and Randi Bry
Interview Transcript with Richard Peterson and Paul Gordon with Con
Warren
Interview Transcripts with Conrad Kohrs Warren
Condition of Windows Report
Correspondence

**Folder 013. HS2 [Photographic Documentation List of Projects for HS2],
1977**

This folder contains:

Photographic Documentation List of Projects for HS2

Folder 014. HS2 [Foundation Repair Projects Duplicate Photographs], 2001-2003

This folder contains:

Condition of Foundation HS2 Duplicate Photographs 2001
Foundation Repointing Duplicate Photographs 2003

Series 003 *PROJECTS RELATED TO HS3 BLACKSMITH SHOP, 1972-2005*

Folder 001. HS3 [Documentation of Projects for HS3 1972-2005], 1972-2005

This folder contains:

National Historic House Specifications 2005
Work Request Logs
Purchase Order for Roof Materials
Research Materials for Roof Materials
Architectural Drawings and Photograph Copies
Correspondence
Completion Report for Stabilize Foundation Project
Assessment of Effect Forms
Blacksmith Shop Door Repair 1995
Compliance Review Form for Repair Damaged Windows
Work Plan and Sequence of Events for Stabilization of Public Restrooms
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1987

Folder 002. HS2 [Duplicate Photographs and Photograph Logs], 1995

This folder contains:

Duplicate Photographs of HS3 Roof Repair
Photograph Logs

Series 004 *PROJECTS RELATED TO HS4 COAL SHED, 1981-2005*

Folder 001. HS4 [Documentation of Projects for HS4 1981-2005], 1981-2005

This folder contains:

List of Projects for HS4 by Date
Work Request Logs
Completion Report for Rehab Foundation Project
Assessment of Effect Forms for Rehabilitate Foundation
Compliance Review Form for Reroof Project
National Historic House Specifications 2005
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1987

Folder 002. HS4 [Oversize Archive Separation Sheets], 5/28/2009

This folder contains:

Archives and Manuscript Collections Separation Sheet for Blueprint of Coal Shed

Folder 003. HS4 [Duplicate Photographs and Photograph Logs], 1988-2003

This folder contains:

Duplicate photographs of HS4 Reroof Project 2003
Photograph Log Sheets

*Series 005 PROJECTS RELATED TO HS5 ICE HOUSE, 1974-2005***Folder 001. HS5 [Historic Structure Report: Architectural Data Section Draft 1978], 1978**

This folder contains:

Draft copy of historic structure report: architectural data section for Ice House Building HS5 1978 Architectural Drawings are included with report

Folder 002. HS5 [Documentation of Projects for HS5 1974-2005], 1974-2005

This folder contains:

National Historic House Specifications 2005
List of Projects for HS5 by Date
Work Request Logs
Condition of Windows Report 1974
Correspondence
Assessment of Actions for Whitewashing Project
Completion Report for Repainting Historic Structures Project
Scope of Work for Repair Daubing Project
Whitewash Formula
Chinese Writing Translation Report
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1987

Folder 003. HS5 [Duplicate Photographs and Photograph Logs], Unknown

This folder contains:

Duplicate photographs of roof repair project for HS5

*Series 006 PROJECTS RELATED TO HS6 GRAINARY, 1975-2006***Folder 001. HS6 [Documentation of Projects for HS6 1975-2006], 1975-2006**

This folder contains:

National Historic House Specifications 2005

Work Request Logs
GRKO Lead Plan for FY 06 Project
PMIS Form for Repaint Exterior of Five Historic Structures
Work Performed on Buildings 2001
Compliance Review Form for Stabilization of Foundations for Five Historic Structures 2000
Assessment of Actions- Concrete Well
PMIS Form for Reroof three historic structures
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1987
Architectural Drawings
Contract for Delivery of 33 cubic yards of five bag mix concrete
Architectural Drawings of Posts for HS6

Folder 002. HS6 [Oversize Archive Separation Sheets], 5/28/2009

This folder contains:

Archives and Manuscript Collections Separation Sheet of 1979 Blueprint for HS6

Folder 003. HS6 [Duplicate Photographs and Photograph Logs], 2001-2003

This folder contains:

Foundation Repair Project Duplicate Photographs 2001
Roof Repair Project Duplicate Photographs 2003
Photograph Logs

Series 007 *PROJECTS RELATED TO HS7 DRAFT HORSE BARN, 1975-2005*

Folder 001. HS7 [Completion Report of Stabilization November 1983], 11/1/1983

This folder contains:

Completion Report of Stabilization for Draft Horse Barn HS7 1983

Folder 002. HS7 [Documentation of Projects for HS7 1975-2005], 1975-2005

This folder contains:

Compliance Review Form for Drainage of Barn Floor 1997
Compliance Review Form for Repair Daubing on Log Buildings 2001
Repair Masonry at Northwest Corner 1997
Work Request Logs
Architectural Drawings and Photograph Copies
Correspondence
Assessment of Actions Forms
Completion Sheets for Redwood and Heating in HS7 and HS65
Compliance Review Form for Installation of Electrical System 1997
Completion Report for Stabilize HS7 Draft Horse Barn

Scope of Work for Repair of Daubing 1997
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1986
National Historic House Specifications 2005

Folder 003. HS7 [Duplicate Photographs and Photograph Logs], 1987-2004

This folder contains:
1987 Repair Floor Duplicate Photographs
1997 Existing Urine Flooded Floor Duplicate Photographs
1997 Existing Slots cut in Floor Duplicate Photographs
2004 Repair of West Horse Door Duplicate Photographs

Series 008 *PROJECTS RELATED TO HS8 PRIVY, 1976-2005*

Folder 001. HS8 [Documentation of Projects for HS8 1976-2005], 1976-2005

This folder contains:
Work Request Logs
Assessment of Actions for Restoration of HS8
Correspondence
Historic Structure Preservation Guide 1982
Maintenance Inspection Forms 1984-1986
National Historic House Specifications 2005

Folder 002. HS8 [Oversize Archive Separation Sheets], 6/2/2009

This folder contains:
Archives and Manuscript Collections Separation Sheet Newspaper Clipping
"Rural Nevadans retain fondness for Privies" The Montana Standard Sunday
March 5, 2000

**Folder 003. HS8 [Duplicate Photographs and Photograph Logs],
Unknown**

This folder contains:
Reference to Photo File Log

Series 009 *PROJECTS RELATED TO HS9 DAIRY BARN, 1975-2008*

Folder 001. HS9 [Documentation of Projects for HS9 1975-2008], 1975-2008

This folder contains:
Work Request Logs
Contract for delivery of 33 cubic yards of five bag mix concrete 2000
Purchase Order for Repainting six historic structures
Scope of Work Reroof, Paint and Gable Trim HS9
Compliance Review Form for Install Metal Ridge Cap on HS9

Compliance Review Form for Stabilize Foundations on five historic structures

Correspondence

Maintenance Inspection Forms 1984-1987

Historic Structure Preservation Guides 1982

National Historic House Specifications 2005

Window/Door Repair and Repainting 2008

Folder 002. HS9 [Oversize Archive Separation Sheets], 5/28/2009

This folder contains:

Archives and Manuscript Collections Separation Sheet for 1979 Blueprint of HS9

Folder 003. HS9 [Duplicate Photographs and Photograph Logs], 1997-2001

This folder contains:

Dairy Barn Replacement of Shingles 1997 Duplicate Photographs

Foundation Repair 2000 Duplicate Photographs

Paint Eave and Gable Trim and Lean-to Duplicate Photographs

Damage to building from a vehicle 2001 Duplicate Photographs

Reference to Photo File

Box 2

Series 010 *PROJECTS RELATED TO HS10 OXEN BARN, 1978-2005*

Folder 001. HS10 [Documentation of Projects for HS10 1978-2005], 1978-2005

This folder contains:

Work Request Logs

Scope of Work for Repair Daubing on seven historic structures

Documentation of Restoration of HS10 Oxen Barn 1981

National Historic House Specifications 2005

Foundation Repairs to dry laid stone and grading for proper drainage

Maintenance Inspection Forms 1984-1987

Historic Structure Preservation Guides 1981-1982

Architectural Drawing

Shingles not to be used for HS10 reference

Folder 002. HS10 [Duplicate Photographs and Photograph Logs], 2005

This folder contains:

Oxen Barn Window Repair: Window Before Repair 2005 Duplicate Photograph

Building a Barrier Between HS10 and HS7 Duplicate Photograph

Improving Water Drainage Duplicate Photograph

Series 011 *PROJECTS RELATED TO HS11 HORSE BARN (BIELENBERG BARN), 1975-2005*

Folder 001. HS11 [Documentation of Projects for HS11 1975-2005], 1975-2005

This folder contains:

Work Request Logs
Correspondence
Historical Find During Excavation Memo 1983
Light Fixture Material Specifications
Assessment of Actions for Preservation Maintenance on HS11
Assessment of Actions for Whitewashing HS11 1982
Completion Report to Maintain Cultural Resources 1984
Completion Report to Square, Replace Supports and Reroof HS11 1984
Completion Report to Repaint Historic Structures 1993
Compliance Review Form for Repair Damaged Windows 1998
Whitewash Formula
Architectural Drawings
Maintenance Inspection Forms 1984-1987
Historic Structure Preservation Guides 1982
Compliance Review Form for Reroof HS11 2003
National Historic House Specifications 2005

Folder 002. HS11 [Duplicate Photographs and Photograph Logs], 1979

This folder contains:

Existing Conditions of HS11 1979 Duplicate Photographs

Series 012 *PROJECTS RELATED TO HS12 MACHINE SHED, 1978-2005*

Folder 001. HS12 [Documentation of Projects for HS12 1978-2005], 1978-2005

This folder contains:

Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1986
Work Request Logs
Assessment of Action for Board and Batten Siding 1982
Completion Report for Maintain Cultural Resources 1984
Correspondence
Stabilize Support Posts on HS12 2004
National Historic House Specifications 2005

Folder 002. HS12 [Duplicate Photographs and Photograph Logs], 2004

This folder contains:

HS12 Before TECO Repair 2004 Duplicate Photographs
HS12 TECO Ring Repair 2004 Duplicate Photographs

Series 013 *PROJECTS RELATED TO HS13 COW SHED, 1974-2005***Folder 001. HS13 [Documentation of Projects for HS13 1974-2005], 1974-2005**

This folder contains:

Work Request Logs
Interview Transcript with Earl F. Allen and Randi Bry 1982
Completion Report for Maintain Cultural Resources 1984
Completion Report for Repaint of historic structures 1994
Assessment of Effect forms for Cow Shed Preservation Maintenance 1995
Correspondence
National Historic House Specifications 2005
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1987
Architectural Drawings

Folder002. HS13 [Duplicate Photographs and Photograph Logs], 1998-2001

This folder contains:

TECO Repair Duplicate Photographs
Equipment Stored in HS13 Duplicate Photographs
Fence Conditions 1998 Duplicate Photographs
Repaired Fence 2001 Duplicate Photographs

Series 014 *PROJECTS RELATED TO HS14 STALLION BARN, 1975-2005***Folder 001. HS14 [Documentation of Projects for HS14 1975-2005], 1975-2005**

This folder contains:

Work Request Logs
Correspondence
South Side of HS14 Barn Reshingled 1999
Compliance Review for Repair Daubing on Log Buildings 2001
Assessment of Effect for Whitewashing Buildings 1982
Culvert South of HS14 Report
Interview Transcript with Con Warren 1985
Interview Transcript with Earl F. Allen and Randi Bry 1982
Architectural Drawings
Completion Report for Repaint historic structures 1994
Scope of Work for Repair Daubing 1997
Whitewash Formula
National Historic House Specifications 2005
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1986

002. HS14 [Duplicate Photographs and Photograph Logs], Unknown

This folder contains:

Roof Repair Duplicate Photographs
Reference to Photo File

Series 015 *PROJECTS RELATED TO HS15 THOROUGHBRED BARN, 1975-2005***Folder 001. HS15 [1988 Thoroughbred Barn Construction Contract Included Specifications of HS15 1987], 1987-1988**

This folder contains:

1988 Thoroughbred Barn Construction Contract Included Specifications of HS15 1987

Folder 002. HS15 [Documentation of Projects for HS15 1975-2005], 1975-2005

This folder contains:

Correspondence

National Historic House Specifications 2005

Compliance Review Form for Improved UV Protection 2001

Work Request Logs

Architectural Drawings

Interview Transcript Earl F. Allen and Randi Bry 1982

Interview Transcripts Conrad Warren 1975-1976

Purchase Order for Wire 1977

HS15 Prior Roof Documentation 1978

Assessment of Effect for Replacing Wooden Floor

Completion Report for Repaint Historic Structures 1994

Compliance Review Form for Reroof HS15 1997

Historic Structure Preservation Guides 1982

Maintenance Inspection Forms 1984-1987

Folder 003. HS15 [Oversize Archive Separation Sheets], 5/28/2009

This folder contains:

Archives and Manuscript Collections Separation Sheets for Blueprint for Structure Stabilization Moving Plan 1988

Folder 004. HS15 [Duplicate Photographs and Photograph Logs], 1988-1998

This folder contains:

Roofing Project 1998 Duplicate Photographs

Object Photograph Record Sheets 1988

Series 016 *PROJECTS RELATED TO HS16 STALLION BARN (LEEDS-LION), 1976-2005***Folder 001. HS16 [Documentation of Projects for HS16 1976-2005], 1976-2005**

This folder contains:

Painting Cedar Roof 1999

Whitewash Formula

Scope of Work Daubing 1997

National Historic House Specifications 2005

Compliance Review Form for Repair Daubing Log Buildings 2001
Historic Structure Preservation Guides 1982
Maintenance Inspection Form 1984-1986
Work Request Logs
Documentation of Stabilization of HS16 Stallion Barn 1982
Interview Transcript Earl F. Allen and Randi Bry 1982
Completion Report Restore HS16 Sill Logs 1983
Assessment of Effect for Whitewashing Buildings 1982
Completion Report Repaint historic structures 1994

**Folder 002. HS16 [Duplicate Photographs and Photograph Logs],
Unknown**

This folder contains:
Reference to photo file for HS16

Series 017 *PROJECTS RELATED TO HS17 BUGGY SHED, 1976-2005*

**Folder 001. HS17 [Documentation of Projects for HS17 1976-2005],
1976-2005**

This folder contains:
Work Request Logs
Assessment of Actions for Whitewashing Structures 1982
Completion Report for Repainting Historic Structures 1994
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1986
National Historic House Specifications 2005
PMIS Form for Stabilization of Support Posts on Three Historic Buildings
2004

Folder 002. HS17 [Oversize Archive Separation Sheets], 5/28/2009

This folder contains:
Archives and Manuscript Collections Separation Sheet of Blueprint for HS17
HABS Drawing 1979

003. HS17 [Duplicate Photographs and Photograph Logs], 2004

This folder contains:
HS17 Support Post Project 2004 Duplicate Photographs
Reference to Photo Files List

Series 018 *PROJECTS RELATED TO HS18 GRAINARY, 1975-2005*

**Folder 001. HS18 [Documentation of Projects for HS18 1975-2005],
1975-2005**

This folder contains:
National Historic House Specifications 2005
Reshingled HS18 Roof 1999
Painting HS18 Cedar Roof, Oiled with Linseed Oil 1999

Work Request Logs
Correspondence
Assessment of Effect for Stabilization of HS2 and HS18 1984
Completion Report for Repainting Historic Structures 1994
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1986

Folder 002. HS18 [Oversize Archive Separation Sheets], 5/28/2009

This folder contains:

Archives and Manuscript Collections Separation Sheet of Blueprint for HS18
HABS Drawing 1979

**Folder 003. HS18 [Duplicate Photographs and Photograph Logs],
Unknown**

This folder contains:

Reference to Photo File for HS18

Series 019 *PROJECTS RELATED TO HS19 STALLION BARN, 1978-2008*

**Folder 001. HS19 [Documentation of Projects for HS19 1978-2008],
1978-2008**

This folder contains:

Architectural Drawings and Photograph Copies
National Historic House Specifications 2005
Roofing HS19 South Side Reshingled 1999
Painting HS19 Cedar Roof Oiled with Linseed Oil 1999
Window and Door Repair and Repainting Project 2008
Installation of TV Display in HS19 Project 2008
Work Request Logs
Correspondence
Assessment of Effect for Structures Requiring Whitewashing 1982
Dismantle walk in door on east side of lean-to on HS19 1981
Completion Report for Repainting of Historic Structures 1994
Whitewash Formula
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1987
Work Performed on HS19 by Date List

**Folder 002. HS19 [Duplicate Photographs and Photograph Logs],
Unknown**

This folder contains:

HS19 Roof Repair Project Duplicate Photographs
Reference to Photo File for HS19

Series 020 *PROJECTS RELATED TO HS20 PRIVY, 1975-2005***Folder 001. HS20 [Documentation of Projects for HS20 1975-2005], 1975-2005**

This folder contains:

Work Request Logs
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1986
National Historic House Specifications 2005

Folder 002. HS20 [Duplicate Photographs and Photograph Logs], 2005

This folder contains:

HS20 Reroofing Project 2005 Duplicate Photographs

Series 021 *PROJECTS RELATED TO HS 21 BROODING HOUSE, 1976-2005***Folder 001. HS21 [Documentation of Projects for HS21 1976-2005], 1976-2005**

This folder contains:

Work Request Logs
Purchase Orders for Paint 1977
Correspondence
Assessment of Actions for Reroofing HS21 1982
Architectural Drawings and Photograph Copies
Scope of Work Repair West Door on HS21
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1987
Compliance Review Form for Stabilization of Foundations on five Historic Structures 2000
National Historic House Specifications 2005
Contract for delivery of 33 cubic yards of five bag mix concrete
Compliance Review Form for Reroof of Three Historic Structures 2003
Work Performed on HS21 by Willies Crew 2001

Folder 002. HS21 [Duplicate Photographs and Photograph Logs], 2001-2003

This folder contains:

Foundation Repair on HS21 2001 Duplicate Photographs
Reroof Project on HS21 2003 Duplicate Photographs
Reference to Photo File List for HS21

Series 022 *PROJECTS RELATED TO HS22 CHICKEN HOUSE, 1976-2005***Folder 001. HS22 [Documentation of Projects for HS22 1976-2005], 1976-2005**

This folder contains:

Work Request Logs
Purchase Orders for Paint 1977

Correspondence

Assessment of Actions for Reroofing HS22 1982

Historic Structure Preservation Guides 1982

Maintenance Inspection Forms 1984-1987

National Historic House Specifications 2005

Compliance Review Form for Stabilization of Foundations on five Historic Structures 2000

Contract for delivery of 33 cubic yards of five bag mix concrete

Compliance Review Form for Reroof three historic structures 2003

Work Performed on Buildings by Willie's Crew Form 2001

Folder 002. HS22 [Duplicate Photographs and Photograph Logs], 2001-2003

This folder contains:

Foundation Repair on HS22 2001 Duplicate Photographs

Reroof Project on HS22 2003 Duplicate Photographs

Series 023 *PROJECTS RELATED TO HS23 GRAINARY, 1975-2005***Folder 001. HS23 [Documentation of Projects for HS23 1975-2005], 1975-2005**

This folder contains:

Work Request Logs

Historic Structure Preservation Guides 1982

Maintenance Inspection Forms 1984-1986

Proposed Project for HS23 1996 Form

Scope of Work for Patching of Bullet Holes in HS23 Architectural Drawings

Compliance Review Form for Store Contaminated Soil 2000

National Historic House Specifications 2005

Folder 002. HS23 [Oversize Archive Separation Sheets], 5/28/2009

This folder contains:

Archives and Manuscript Collections Separation Sheet for Blueprint of HS23 HABS Drawing 1979

Folder 003. HS23 [Duplicate Photographs and Photograph Logs], 1997

This folder contains:

Rehab Grainary Project 1997 Duplicate Photographs

Reference Log to Photo File for HS23

Series 024 *PROJECTS RELATED TO HS24 STOCK SHELTER, 1981-2005***Folder 001. HS24 [Documentation of Projects for HS24 1981-2005], 1981-2005**

This folder contains:

Work Request Logs

Assessment of Actions for Preservation Maintenance 1983

Completion Report for Maintain Cultural Resources 1984

Completion Report for Rehabilitate Historic Cow Sheds HS24, 27, 29, 32, 33
1984
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1986
National Historic House Specifications 2005
Compliance Review Form for Reroof five cowsheds 2001
Compliance Review Form for Replace support posts on HS24 2001

Series 025 *PROJECTS RELATED TO HS25 STOCK SHELTER, 1981-2005*

**Folder 001. HS25 [Documentation of Projects for HS25 1981-2005],
1981-2005**

This folder contains:

Work Request Logs
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1986
Compliance Review Form Stabilize HS25 Stock Shelter and HS26 Hay
Storage 2000
National Historic House Specifications 2005
Architectural Drawings

Folder 002. HS25 [Duplicate Photographs and Photograph Logs], 2000

This folder contains:

Reconstruction of HS25 2000 Duplicate Photographs

Series 026 *PROJECTS RELATED TO HS26 HAY STORAGE, 1981-2005*

**Folder 001. HS26 [Documentation of Projects for HS26 1981-2005],
1981-2005**

This folder contains:

Work Request Logs
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1986
Compliance Review Form for Stabilization of HS25 Stock Shelter and HS26
Hay Storage 2000
National Historic House Specifications 2005

Folder 002. HS26 [Duplicate Photographs and Photograph Logs], 2000

This folder contains:

Rebuilding Hay Storage HS26 2000 Duplicate Photographs

Series 027 *PROJECTS RELATED TO HS27 STOCK SHELTER, 1980-2005*

**Folder 001. HS27 [Documentation of Projects for HS27 1980-2005],
1980-2005**

This folder contains:

Work Request Logs
Completion Report for Maintain Cultural Resources 1984

Completion Report for Rehabilitate Historic Cow Sheds HS24, 27, 29, 32, 33
1983
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1986
Assessment of Actions for Preservation Maintenance 1983
Architectural Drawings
Work Performed on Buildings by Willie's Crew for Removal of Existing
Boards for HS27 2002
PMIS Form for Reroof of five cow sheds 2001
National Historic House Specifications 2005

Folder 002. HS27 [Duplicate Photographs and Photograph Logs], 1999-2000

This folder contains:
HS27 Duplicate Photographs 1999-2000

Series 028 *PROJECTS RELATED TO HS28 FEED STORAGE HOUSE, 1977-2005*

Folder 001. HS28 [Documentation of Projects for HS28 1977-2005], 1977-2005

This folder contains:
Work Request Logs
Purchase Orders for Paint 1977
Scope of Work for Split Door Project
Correspondence
Architectural Drawings
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1986
National Historic House Specifications 2005

Folder 002. HS28 [Duplicate Photographs and Photograph Logs], 2001

This folder contains:
Foundation Repairs to HS28 2001 Duplicate Photographs

Series 029 *PROJECTS RELATED TO HS29 STOCK SHELTER, 1980-2005*

Folder 001. HS29 [Documentation of Projects for HS29 1980-2005], 1980-2005

This folder contains:
Work Request Logs
Completion Report for Rehabilitate Historic Cow Sheds HS24, 27, 29, 32, 33
1984
Completion Report for Maintain Cultural Resources 1984
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1987
Assessment of Actions for Preservation Maintenance 1983
PMIS Form for Reroof five cow sheds 2001

Work Performed on Buildings by Willie's Crew for Removal of Boards in
HS29 2002
National Historic House Specifications 2005

Series 030 *PROJECTS RELATED TO HS30 STALLION BARN, 1979-2008*

**Folder 001. HS30 [Documentation of Projects for HS30 1979-2008],
1979-2008**

This folder contains:
Work Request Logs
Correspondence
Assessment of Actions for Reroof HS30 1982
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1986
Window Repair and Repainting of HS30 2008
National Historic House Specifications 2005

**Folder 002. HS30 [Duplicate Photographs and Photograph Logs],
Unknown**

This folder contains:
Reference to Photo File for HS30

Series 031 *PROJECTS RELATED TO HS31 FEED STORAGE HOUSE, 1977-2005*

**Folder 001. HS31 [Documentation of Projects for HS31 1977-2005],
1977-2005**

This folder contains:
Work Request Logs
Purchase Orders for Paint 1977
Correspondence
Maintenance Inspection Forms 1984-1987
Historic Structure Preservation Guides 1982
National Historic House Specifications 2005
Compliance Review Form for Stabilization of Foundations on five historic
structures 2000
Work Performed on Buildings by Willie's Crew Form for Replacement of
Foundation in HS31 2001
HS31 Strip and Reroof Cedar Shingles Project 2006
Contract for delivery of 33 cubic yards of five bag mix concrete
Architectural Photograph Copies

Folder 002. HS31 [Duplicate Photographs and Photograph Logs], 2001

This folder contains:
Foundation Repair on HS31 2001 Duplicate Photographs
Reference to Photo File for HS31

Series 032 *PROJECTS RELATED TO HS32 STOCK SHELTER, 1981-2005*

**Folder 001. HS32 [Documentation of Projects for HS32 1981-2005],
1981-2005**

This folder contains:

Work Request Logs
Completion Report for Maintain Cultural Resources 1984
Completion Report for Rehabilitate Historic Cow Sheds HS24, 27, 29, 32, 33
1984
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1987
Assessment of Actions for Preservation Maintenance 1983
Work Performed on Buildings by Willie's Crew for Removal of Boards from
HS32 2002
PMIS Form for Reroof five cow sheds 2001
National Historic House Specifications 2005

Series 033 *PROJECTS RELATED TO HS33 STOCK SHELTER, 1981-2005*

**Folder 001. HS33 [Documentation of Projects for HS33 1981-2005],
1981-2005**

This folder contains:

Work Request Logs
Completion Report for Rehabilitate Historic Cow Sheds HS24, 27, 29, 32, 33
1984
Completion Report for Maintain Cultural Resources 1984
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1987
PMIS Form for Reroof five cow sheds 2001
Work Performed on Buildings by Willie's Crew for Removal of Boards in
HS33 2002
National Historic House Specifications 2005

Series 034 *PROJECTS RELATED TO HS34 STORAGE SHED, 1978-2008*

**Folder 001. HS34 [Documentation of Projects for HS34 1978-2008],
1978-2008**

This folder contains:

Work Request Logs
Interview Transcript with Con Warren, Jim Taylor, and Randi Bry 1983
Project Information Sheet for Rehabilitate Storage Shed HS34 1990
Correspondence
Assessment of Effect on Rehabilitate Storage Shed HS34 1990
Historic Structure Preservation Guides 1982
Maintenance Inspection Forms 1984-1987
Window Cleaning for HS34 2008

Architectural Photograph Copies
National Historic House Specifications 2005

Series 035 *PROJECTS RELATED TO HS35 CATTLE SCALE, 1975-2008*

**Folder 001. HS35 [Documentation of Projects for HS35 1975-2008],
1975-2008**

This folder contains:

Work Request Logs
Completion Report for Rehabilitate HS35 Cattle Scale and HS40 Beef Hoist
1983
Architectural Photograph Copies
Maintenance Inspection Forms 1982-1986
Rebuild/Restore Entire Cattle Scale 2008
National Historic House Specifications 2005

Series 036 *PROJECTS RELATED TO HS36 FEED RACK, 1982-2005*

**Folder 001. HS36 [Documentation of Projects for HS36 1982-2005],
1982-2005**

This folder contains:

Work Request Logs
Correspondence
Completion Report for Rehabilitate Feed Racks HS36, 37, 38, 43, 44 1984
Maintenance Inspection Forms 1982-1986
National Historic House Specifications 2005

Series 037 *PROJECTS RELATED TO HS37 FEED RACK, 1982-2005*

**Folder 001. HS37 [Documentation of Projects for HS37 1982-2005],
1982-2005**

This folder contains:

Work Request Logs
Correspondence
Completion Report for Rehabilitate Feed Racks HS36, 37, 38, 43, 44 1984
Maintenance Inspection Forms 1982-1986
National Historic House Specifications 2005

Series 038 *PROJECTS RELATED TO HS38 FEED RACK, 1982-2005*

**Folder 001. HS38 [Documentation of Projects for HS38 1982-2005],
1982-2005**

This folder contains:

Work Request Logs
Correspondence
Completion Report for Rehabilitate Feed Racks HS36, 37, 38, 43, 44 1984

Maintenance Inspection Forms 1982-1986
Architectural Drawings
National Historic House Specifications 2005

Folder 002. HS38 [Duplicate Photographs and Photograph Logs], 2004

This folder contains:
Replacement of Logs on HS38 2004 Duplicate Photographs

Series 039 *PROJECTS RELATED TO HS39 MANURE PIT, 1975-2005*

**Folder 001. HS39 [Documentation of Projects for HS39 1975-2005],
1975-2005**

This folder contains:
Work Request Logs
Maintenance Inspection Forms 1982-1986
National Historic House Specifications 2005

Series 040 *PROJECTS RELATED TO HS40 BEEF HOIST, 1982-2008*

**Folder 001. HS40 [Documentation of Projects for HS40 1982-2008],
1982-2008**

This folder contains:
Work Request Logs
Completion Report for Rehabilitate HS35 Cattle Scale and HS40 Beef Hoist
1983
Architectural Drawings and Photograph Copies
Maintenance Inspection Forms 1982-1986
Replace Rotted Flooring, Rails, and Hoist for HS40 2008
National Historic House Specifications 2005

Series 041 *PROJECTS RELATED TO HS41 SQUEEZE CHUTE, 1976-2008*

**Folder 001. HS41 [Documentation of Projects for HS41 1976-2008],
1976-2008**

This folder contains:
Work Request Logs
Interview Transcript with Con Warren 1981
Completion Report for Maintain Cultural Resources 1984
Completion Report for Rehabilitate 3 Cattle Chutes 1984
Correspondence
Architectural Drawings and Photograph Copies
Assessment of Actions for Restoration of Squeeze Chutes 1982
Maintenance Inspection Forms 1982-1986
Preserve/Repair Squeeze Chute 2008
Corral Header Supports Replacement 2008
National Historic House Specifications 2005

Series 042 *PROJECTS RELATED TO HS42 FEED RACK, 1975-2005*

Folder 001. HS42 [Documentation of Projects for HS42 1975-2005], 1975-2005

This folder contains:
Work Request Logs
Maintenance Inspection Forms 1982-1986
Architectural Drawings and Photograph Copies
National Historic House Specifications 2005

Series 043 *PROJECTS RELATED TO HS43 FEED RACK, 1982-2005*

Folder 001. HS43 [Documentation of Projects for HS43 1982-2005], 1982-2005

This folder contains:
Work Request Logs
Correspondence
Completion Report for Rehabilitate Feed Racks HS36, 37, 38, 43, 44 1984
Maintenance Inspection Forms 1982-1986
National Historic House Specifications 2005

Series 044 *PROJECTS RELATED TO HS44 FEED RACK, 1982-2005*

Folder 001. HS44 [Documentation of Projects for HS44 1982-2005], 1982-2005

This folder contains:
Work Request Logs
Correspondence
Completion Report for Rehabilitate Feed Racks HS36, 37, 38, 43, 44 1984
Maintenance Inspection Forms 1982-1986
Architectural Drawings
National Historic House Specifications 2005

Folder 002. HS44 [Duplicate Photographs and Photograph Logs], 2004

This folder contains:
Replacement of Logs on HS44 2004 Duplicate Photographs

Series 045 *PROJECTS RELATED TO HS45 FEED BUNKER, 1978-2005*

Folder 001. HS45 [Documentation of Projects for HS45 1978-2005], 1978-2005

This folder contains:
Work Request Logs
Interview Transcripts with Con Warren 1978
Correspondence

Working Drawings of HS45 and HS46 Summer 1991
Reconstruction Maintenance Inspection Forms 1982-1986
PMIS Form for Stabilize five historic feed bunks HS45, 46, 49, 52 2004
Architectural Drawings and Photograph Copies
National Historic House Specifications 2005

Folder 002. HS45 [Oversize Archive Separation Sheets], 5/28/2009

This folder contains:

Archives and Manuscript Collections Separation Sheet for Mylar Sheet for
Typical Construction on HS45 and HS46

Series 046 *PROJECTS RELATED TO HS46 FEED BUNKER, 1978-2005*

**Folder 001. HS46 [Documentation of Projects for HS46 1978-2005],
1978-2005**

This folder contains:

Work Request Logs
Interview Transcript of Con Warren 1978
Correspondence
Maintenance Inspection Forms 1982-1986
PMIS Form for Stabilize five historic feed bunks HS45, 46, 49, 52 2004
Architectural Drawings
National Historic House Specifications 2005

002. HS46 [Oversize Archive Separation Sheets], 5/28/2009

This folder contains:

Archives and Manuscript Collections Separation Sheet for Mylar copy of
Typical Construction on HS 45 and HS46

003. HS46 [Duplicate Photographs and Photograph Logs], 2004

This folder contains:

Removal of Rotten Material on HS46 2004 Duplicate Photographs

Series 047 *PROJECTS RELATED TO HS47 SQUEEZE CHUTE, 1982-2008*

**Folder 001. HS47 [Documentation of Projects for HS47 1982-2008],
1982-2008**

This folder contains:

Work Request Logs
Completion Report for Maintain Cultural Resources 1984
Completion Report for Rehabilitate 3 Cattle Chutes 1984
Architectural Drawings
Assessment of Actions for Restoration of Squeeze Chutes 1982
Maintenance Inspection Forms 1982-1986
Preserve/Maintain Squeeze Chute Project 2008
National Historic House Specifications 2005

Series 048 *PROJECTS RELATED TO HS48 FEED BUNKER, 1982-2005*

Folder 001. HS48 [Documentation of Projects for HS48 1982-2005], 1982-2005

This folder contains:

Work Request Logs

Correspondence

Completion Report for Repair Deteriorated Feed Bunks HS48 and HS49 1986

Case Incident Report for a Horse Stuck in a Fence 1988

Maintenance Inspection Forms 1982-1986

Architectural Drawings and Photograph Copies

HS48 and HS49 Feed Bunk Repairs and New Apron Construction 1995

PMIS Form for Stabilize five historic feed bunks HS45, 46, 48, 49, 52 2004

National Historic House Specifications 2005

Folder 002. HS48 [Duplicate Photographs and Photograph Logs], 2004

This folder contains:

Replacement of HS48 Posts and Boards 2004 Duplicate Photographs

Reference to Photo File

Series 049 *PROJECTS RELATED TO HS49 FEED BUNKER, 1981-2005*

Folder 001. HS49 [Documentation of Projects for HS49 1981-2005], 1981-2005

This folder contains:

Work Request Logs

Correspondence

Completion Report for Repair Deteriorated Feed Bunks HS48 and HS49 1986

Architectural Drawings and Photograph Copies

HS48 and HS49 Feed Bunk Repairs and New Apron Construction 1995

Maintenance Inspection Forms 1982-1986

PMIS Form for Stabilize five historic feed bunks HS45, 46, 48, 49, 52 2004

National Historic House Specifications 2005

Folder 002. HS49 [Duplicate Photographs and Photograph Logs], 2004

This folder contains:

HS49 Feed Bunk Repair to Gate 2004 Duplicate Photographs

Reference to Photo File

Series 050 *PROJECTS RELATED TO HS50 FLUME, ACTIVE, 1982-2005*

Folder 001. HS50 [Documentation of Projects for HS50 1982-2005], 1982-2005

This folder contains:

Work Request Logs
The Kohrs-Manning Ditch Information 1990
Correspondence
Maintenance Inspection Forms 1982-1984
National Historic House Specifications 2005

Series 051 *PROJECTS RELATED TO HS51 FLUME, INACTIVE, 1976-2001*

**Folder 001. HS51 [Documentation of Projects for HS51 1976-2001],
1976-2001**

This folder contains:
Work Request LogsHS51 Flume Removed 1976
Architectural Drawing
Correspondence
Maintenance Inspection Forms 1982-1984

Series 052 *PROJECTS RELATED TO HS52 FEED BUNKER, 1976-2005*

**Folder 001. HS52 [Documentation of Projects for HS52 1976-2005],
1976-2005**

This folder contains:
Work Request Logs
Correspondence
Completion Report for Repair Feed Bunk HS52 1986
Maintenance Inspection Forms 1982-1986
PMIS Form for Stabilize five historic feed bunks HS45. 46, 48, 49, 52 2004
Architectural Drawings
National Historic House Specifications 2005

Series 053 *PROJECTS RELATED TO HS53 SQUEEZE CHUTE, 1976-2008*

**Folder 001. HS53 [Documentation of Projects for HS53 1976-2008],
1976-2008**

This folder contains:
Work Request Logs
Assessment of Actions for Restoration of Squeeze Chutes HS 41, 47, 53 1982
Correspondence
Completion Report for Maintain Cultural Resources 1984
Completion Report for Rehabilitate 3 Cattle Chutes 1984
Architectural Drawings
Maintenance Inspection Forms 1982-1986
HS53 Squeeze Chute Replace Rotted Material 2008
National Historic House Specifications 2005

Series 054 *PROJECTS RELATED TO HS54 BRIDGE, 1994*

Folder 001. HS54 [Documentation of Projects for HS54 1994], 1994

This folder contains:

Correspondence Related to Bridge over Johnson Creek 1994

Box 3

Series 055 *PROJECTS RELATED TO HS55 BRIDGE, 1980-2005*

Folder 001. HS55 [Documentation of Projects for HS55 1980-2005], 1980-2005

This folder contains:

Work Request Logs

Bridge Safety Inspection Report Kohrs-Manning Ditch Bridge 1980

Bridge Maintenance Report 1981

Bridge, Tunnel, and Culvert Inventory 1982

PMIS Form for Repair 3 Historic Bridges 2004

Completion Report for Redeck 3 Bridges 1982

Architectural Photograph Copies

Maintenance Inspection Forms 1982-1986

National Historic House Specifications 2005

Series 056 *PROJECTS RELATED TO HS56 RAILROAD, 1985-2005*

Folder 001. HS56 [Documentation of Projects for HS56 1985-2005], 1985-2005

This folder contains:

Work Request Logs

Information on Railroad Rails

Interview Transcript with Con Warren 1989

Maintenance Inspection Forms 1986

National Historic House Specifications 2005

Series 057 *PROJECTS RELATED TO HS57 SIPHON, 2005*

Folder 001. HS57 [National Historic House Specifications 2005], 2005

This folder contains:

National Historic House Specifications 2005

PROJECTS RELATED TO HS58 WARREN HOUSE, 1994-2005

001. HS58 [HS58 Grounds Maintenance 1995-2003], 1995-2003

This folder contains:

Correspondence

Related to Replanting of the Cottonwood Trees 2001

Lanette King Report on Replanting at the Warren House

Response to Specific Concerns on Grounds Maintenance at the Warren House 1995

Folder 002. HS58 [HS58 Warren House Adaptive Reuse 1995], 1995

This folder contains:

Materials List for the Adaptive Reuse of the Warren House 1995HS58
Warren House Adaptive Reuse 1995 Information Packet

Folder 003. HS58 [HS58 Lead Abatement and Repainting 1995-2000], 1995-2000

This folder contains:

PMIS Form for Repaint exterior of five historic buildings, provide for lead reduction 2001
National Park Service Lead Paint Test Report
Lead Paint Chip Analysis Field Notes
Correspondence
Certificate of Analysis from Interwest Analytical Laboratories 1995
PMIS Form for HS58 Lead Abatement 2000
Copies of Photographs of Lead Paint in HS58 Basement 2000
Radon Monitoring Report from Landauer 1996

Folder 004. HS58 [Documentation of Projects for HS58 1994-2005], 1994-2005

This folder contains:

Work Request Logs
PMIS Form for Replace boiler and upgrade heating system HS58 Warren House 2004
Correspondence
Compliance Review Form for Replace obsolete and damaged furnace in HS58 2004
Work Performed on Buildings by Willie's Crew for Replacement of HS58 Picket Fence 2001
Architectural Drawings and Photograph Copies
"SPECIFICATIONS WHICH WITH THE ACCOMPANYING DRAWINGS DESCRIBE A BUNGALOW FOR WOMAN'S HOME COMPANION, Lewis E. Welsh"
Estimated costs for city water and sewer, electrical, carpeting, painting, and ongoing custodial maintenance services
Overall Analysis Assumptions for Warren House
List of Needs for Warren Area Residence and Out Buildings
Architectural Drawing of Electrical Layout of the Warren House Basement 1995
HS58 Downstairs Bathroom Counter Front 1996
PMIS Form for Reroof five Historic Buildings 2001
National Historic House Specifications 2005
Instructions for Water Heater in Warren House

Mylar Architectural Drawing of HS58 Fencing

Folder 005. HS58 [Reroof Project Duplicate Photographs 2002], 2002

This folder contains:

Warren House Reroof Project 2002 Duplicate Photographs

Folder 006. HS58 [Oversize Archive Separation Sheets], 5/28/2009

This folder contains:

Archives and Manuscript Collections Separation Sheet for Con Warren House Basement Electrical Layout 1995

Folder 007. HS58 [Duplicate Photographs and Photograph Logs], 1995-2004

This folder contains:

Basement Lead Abatement 2000 Duplicate Photographs

Warren House Landscape Work 2001 Duplicate Photographs

Warren House Fence Repairs 2001 Duplicate Photographs

Picket Fence Work 2004 Duplicate Photographs

Replacement of Furnace 2004 Duplicate Photographs

Warren House Fence Existing Conditions 1995 Duplicate Photographs

Warren House Basement Communications System 2002 Photograph Copies

Photograph Logs for Projects in Warren House

Series 059 *PROJECTS RELATED TO HS59 CHICKEN COOP, 1995-2008*

Folder 001. HS59 [Documentation of Projects for HS59 1995-2008], 1995-2008

This folder contains:

Work Request Logs

Assessment of Effect Form for Structures Preservation Maintenance 1995

HS59 Chicken Coop Roofing Project 1995

HS59 Chicken Coop Windows Project 1995

Chicken Coop Window and Door Repair and Repainting 2008

Response to Specific Concerns Structures Preservation Maintenance 1995

PMIS Form Repaint exterior of five historic buildings, provide for lead reduction 2001

National Historic House Specifications 2005

Folder 002. HS59 [Oversize Archive Separation Sheets], 6/16/2009

This folder contains:

Archives and Manuscripts Collections Separation Sheet for HS59 Chicken Coop Measurements by Walls and Doors

Folder 003. HS59 [Duplicate Photographs and Photograph Logs], 2002-2003

This folder contains:

Chicken Coop Reroof 2001-2003 Duplicate Photographs
Photograph Logs for HS59 Projects

Series 060 *PROJECTS RELATED TO HS60 BOAT HOUSE, 2001-2008*

Folder 001. HS60 [Documentation of Projects for HS60 2001-2008], 2001-2008

This folder contains:

Correspondence
PMIS Form for Reroof five historic buildings 2001
PMIS Form for Repaint exterior of five historic buildings, provide for lead reduction 2001
HS60 Window Cleaning and Trim Repainting 2008
National Historic House Specifications 2005

Folder 002. HS60 [Duplicate Photographs and Photograph Logs], 2002

This folder contains:

HS60 Boat House Reroof Project 2002 Duplicate Photographs

Series 061 *PROJECTS RELATED TO HS61 WARREN HOUSE GARAGE, 2001-2005*

Folder 001. HS61 [Documentation of Projects for HS61 2001-2005], 2001-2005

This folder contains:

PMIS Form for Repaint exterior of five historic buildings, provide for lead reduction 2001
National Historic House Specifications 2005

Folder 002. HS61 [Duplicate Photographs and Photograph Logs], 1997

This folder contains:

Deteriorating Concrete at HS61 1997 Duplicate Photographs

Series 062 *PROJECTS RELATED TO HS62 BARN, 1994-2005*

Folder 001. HS62 [Documentation of Project for HS62 1994-2005], 1994-2005

This folder contains:

Work Request Logs
Architectural Drawings of Repairs to Windows on HS62 1994
Compliance Review Form for Repaint Bull Barns HS62 and HS63 1997
Assessment of Actions for Paint of HS62 and HS63 Bull Barns 1997
Scope of Work for Repaint Bull Barns HS62 and HS63
National Historic House Specifications 2005

Folder 002. HS62 [Duplicate Photographs and Photograph Logs], 2001

This folder contains:

HS62 Bull Barn Repairs Duplicate Photographs
Fence Repairs 2001 Duplicate Photographs

Series 063 *PROJECTS RELATED TO HS63 BARN, 1994-2005*

Folder 001. HS63 [Documentation of Projects for HS63 1994-2005], 1994-2005

This folder contains:

Work Request LogsHS63 Siding Repair 1995
Architectural Drawings of Window Repairs for HS63 1994
Correspondence
Compliance Review Form for Install Interior Window Protection HS63 Bull Barn 2001
National Historic House Specifications 2005

Folder 002. HS63 [Duplicate Photographs and Photograph Logs], 2001

This folder contains:

HS63 Bull Barn Repair Duplicate Photographs
HS62 Fence Repairs 2001 Duplicate Photographs

Series 064 *PROJECTS RELATED TO HS64 RED BARN, 1989-2005*

Folder 001. HS64 [Reroof HS64 Red Barn Materials 1992-1997], 1992-1997

This folder contains:

Reroof of HS64 Contract Materials 1995

Folder 002. HS64 [Red Barn Roof Bid 1994-1995], 1994-1995

This folder contains:

HS64 Red Barn Reroof Bid for Contractors Materials 1994-1995

Folder 003. HS64 [Documentation of Projects for HS64 1989-2005], 1989-2005

This folder contains:

Work Request Logs
Architectural Drawings
Correspondence
HS64 Barn Door Repairs 1994-1995
Compliance Review Form for Repair Damaged Windows in Red Barn HS64 1997
Interview Transcript of Con Warren 1993
HS64 Installed Eyebolt and Rope to South Door 2001
National Park Service Historic Structure Survey Form 1972
HS64 Chronological Time Line of Projects 1997

Character Defining Elements of HS64
PMIS Form for Repair/Repaint, Doors, Windows, and Trim HS64 2002
National Historic House Specifications 2005

Folder 004. HS64 [Duplicate Photographs and Photograph Logs], 1994-2001

This folder contains:
HS64 Roof Conditions 1994-2001 Duplicate Photographs
Loft Floor Repair 1997 Duplicate Photographs

Series 65 *PROJECTS RELATED TO HS65 METAL BARN, 1991-2005*

Folder 001. HS65 [Documentation of Projects for HS65 1991-2005], 1991-2005

This folder contains:
Work Request Logs
Architectural Drawings and Photograph Copies
Metal Barn Maintenance Shop Material List
Correspondence
Insulation Materials Lists
Commitment Control Register for Rehab Shop HS65
Completion Report for Redwood and Heating 1992
Completion Report for Interior Adaption of HS65 Barn to Maintenance Shop 1992
Architectural Drawings for Window Repair in HS65
Assessment of Effect Form for Electrical Work for HS65
Assessment of Actions for Interior Adaption of HS65 Barn to Maintenance Shop
Case Incident Record for Non-Malicious Damage Shop Door 2000
Compliance Review Form for HS65
Maintenance Shop Furnace Installation 1996
National Historic House Specifications 2005

Folder 002. HS65 [Duplicate Photographs and Photograph Logs], 2000

This folder contains:
HS65 Paint Room Construction 2000 Duplicate Photographs

Series 066 *PROJECTS RELATED TO HS66 SCALE HOUSE, 1980-2005*

Folder 001. HS66 [Documentation of Projects for HS66 1980-2005], 1980-2005

This folder contains:
Work Performed on Buildings by Willie's Crew for Replacement of Door on HS66 2001
Notice to all owners of stock scales from the Department of Commerce 1991
Architectural Drawings
State of Montana Department of Commerce License for HS66 1980-1996

National Historic House Specifications 2005

Folder 002. HS66 [Duplicate Photographs and Photograph Logs], 1990

This folder contains:

Scale House Southwest Corner 1990 Duplicate Photographs

Series 067 *PROJECTS RELATED TO HS67 SQUEEZE CHUTE, 2005-2008*

**Folder 001. HS67 [Documentation of Projects for HS67 2005-2008],
2005-2008**

This folder contains:

Preserve/Repair Squeeze Chute 2008

HS67 LCS File Referring to Revisions by Con Warren

National Historic House Specifications 2005

Folder 002. HS67 [Duplicate Photographs and Photograph Logs], 2002

This folder contains:

HS67 Squeeze Chute 2002 Duplicate Photographs

Series 068 *PROJECTS RELATED TO HS68 FEED RACK, 1990-2005*

**Folder 001. HS68 [Documentation of Projects for HS68 1990-2005],
1990-2005**

This folder contains:

Work Request Logs

Scope of Work for Rebuild HS68 to a Functional Feed Rack

Architectural Photograph Copies

National Historic House Specifications 2005

Series 069 *PROJECTS RELATED TO HS69 LOADING CHUTE, 1993-2005*

**Folder 001. HS69 [Documentation of Projects for HS69 1993-2005],
1993-2005**

This folder contains:

Work Request Logs

Completion Report for Repaint Historic Structures 1993

National Historic House Specifications 2005

Series 070 *PROJECTS RELATED TO HS70 COW SHED, 1980-2005*

**Folder 001. HS70 [Documentation of Projects for HS70 1980-2005],
1980-2005**

This folder contains:

Work Request Logs

Correspondence

Assessment of Actions for Rehabilitate Cow Sheds HS70, 71, 72, 73, 74, 75,
76, 77

Grant Kohrs Ranch Preservation Project

Historical Preservation Project Cow Sheds 1993

PMIS Form for Restore Warren Hereford Ranch Site 2003
Architectural Drawings
Assessment of Actions for Rehabilitate Cow Sheds HS70, 71, 72, 73, 74, 75,
76, 77 1993
Warren Area Feed Lot Fencing 2000
National Historic House Specifications 2005
Project Cost Account Data Entry Sheet 1992 Requisition Forms
Folder 002. HS70 [Duplicate Photographs and Photograph Logs], 2004
This folder contains:
Warren Feed Lots Gate and Fence Repair 2004 Duplicate Photographs
Labels of Photos List for HS70-HS77

Series 071 *PROJECTS RELATED TO HS71 COW SHED, 1993-2005*

**Folder 001. HS71 [Documentation of Projects for HS71 1993-2005],
1993-2005**

This folder contains:

Work Request Logs
Grant Kohrs Ranch Preservation Project Warren Area Feed Lot Fencing 2000
National Historic House Specifications 2005

Series 072 *PROJECTS RELATED TO HS72 COW SHED, 1993-2005*

**Folder 001. HS72 [Documentation of Projects for HS72 1993-2005],
1993-2005**

This folder contains:

Work Request Logs
Grant Kohrs Ranch Preservation Project
Architectural Drawings
Warren Area Feed Lot Fencing 2000
National Historic House Specifications 2005

Series 073 *PROJECTS RELATED TO HS73 COW SHED, 1993-2005*

**Folder 001. HS73 [Documentation of Projects for HS73 1993-2005],
1993-2005**

This folder contains:

Work Request Logs
Grant Kohrs Ranch Preservation Project
Architectural Drawings
Warren Area Feed Lot Fencing 2000
National Historic House Specifications 2005

Series 074 *PROJECTS RELATED TO HS74 COW SHED, 1993-2005*

**Folder 001. HS74 [Documentation of Projects for HS74 1993-2005],
1993-2005**

This folder contains:
Work Request Logs
Grant Kohrs Ranch Preservation Project
Warren Area Feed Lot Fencing 2000
Architectural Drawings
National Historic House Specifications 2005

Series 075 *PROJECTS RELATED TO HS75 COW SHED, 1993-2005*

Folder 001. HS75 [Documentation of Projects for HS75 1993-2005], 1993-2005

This folder contains:
Work Request Logs
Grant Kohrs Ranch Preservation Project
Work Performed on Buildings by Willie's Crew for HS75 Repairs on Roof Truss 2002
Warren Area Feed Lot Fencing 2000
Compliance Review Form for HS75 Cowshed Roof Truss 2001
Architectural Drawings
National Historic House Specifications 2005

Folder 002. HS75 [Duplicate Photographs and Photograph Logs], 2002

This folder contains:
HS75 Roof Truss Repair 2002 Duplicate Photographs

Series 076 *PROJECTS RELATED TO HS76 COW SHED, 1993-2005*

Folder 001. HS76 [Documentation of Projects for HS76 1993-2005], 1993-2005

This folder contains:
Work Request Logs
Grant Kohrs Ranch Preservation Project
Warren Area Feed Lot Fencing 2000
National Historic House Specifications 2005

Series 077 *PROJECTS RELATED TO HS77 COW SHED, 1992-2005*

Folder 001. HS77 [Documentation of Projects for HS77 1992-2005], 1992-2005

This folder contains:
Work Request Logs
Correspondence
Grant Kohrs Ranch Preservation Project
Warren Area Feed Lot Fencing 2000
National Historic House Specifications 2005

Series 078 *PROJECTS RELATED TO HS78 FEED HOUSE, 2005*

Folder 001. HS78 [National Historic House Specifications 2005], 2005

This folder contains:

National Historic House Specifications 2005

Series 079 *PROJECTS RELATED TO HS79 FEED HOUSE, 2005*

Folder 001. HS79 [National Historic House Specifications 2005], 2005

This folder contains:

National Historic House Specifications 2005

Series 080 *PROJECTS RELATED TO HS80 FEED HOUSE, 2005*

Folder 001. HS80 [National Historic House Specifications 2005], 2005

This folder contains:

National Historic House Specifications 2005

Series 081 *PROJECTS RELATED TO HS81 FEED HOUSE, 2005*

Folder 001. HS81 [National Historic House Specifications 2005], 2005

This folder contains:

National Historic House Specifications 2005

Series 082 *PROJECTS RELATED TO HS82 FEED HOUSE, 2005*

Folder 001. HS82 [National Historic House Specifications 2005], 2005

This folder contains:

National Historic House Specifications 2005

Series 083 *PROJECTS RELATED TO HS83 FEED HOUSE, 2005*

Folder 001. HS83 [National Historic House Specifications 2005], 2005

This folder contains:

National Historic House Specifications 2005

Series 084 *PROJECTS RELATED TO HS84 FEED HOUSE, 2005*

Folder 001. HS84 [National Historic House Specifications 2005], 2005

This folder contains:

National Historic House Specifications 2005

Series 085 *PROJECTS RELATED TO HS85 PUMP HOUSE, 1999-2005*

Folder 001. HS85 [Documentation of Projects for HS85 1999-2005], 1999-2005

This folder contains:

Correspondence
Removal of Structure HS85 Pump House
List of Classified Structures Single Entry Report HS85
National Park Service Historic Structure Survey Form for HS85
National Historic House Specifications 2005

*Series 086 PROJECTS RELATED TO HS86 PUMP HOUSE, 1990-2005***Folder 001. HS86 [Documentation of Projects for HS86 1990-2005], 1990-2005**

This folder contains:

HS86 North Pump House Estimated Load in Watts
Structures West of the Tracks HS86 and HS87 1990
Power Removal from HS86 Pump House 2002
Case Incident Record for Vandalism on HS86 Pump House 1999
Correspondence
National Historic House Specifications 2005

Folder 002. HS86 [Duplicate Photographs and Photograph Logs], 1999

This folder contains:

Pump House after being vandalized 1999 Duplicate Photographs

*Series 087 PROJECTS RELATED TO HS87 PUMP HOUSE, 1989-2005***Folder 001. HS87 [Documentation of Projects for HS87 1989-2005], 1989-2005**

This folder contains:

Work Request Logs
Pump House Data Provided by Layne Minnesota 1989
Pump House Data Provided by The Lo-Lift Pump Co. Inc. 1989
HS87 South Pump House Estimated Load in Watts
Quotation for Pump House from Mel's Electric 1994
Rehabilitate West Irrigation System 1995
Correspondence
Completion Report for Emergency Pump Repair 1990
Commitment Control Register Project Completed for Irrigation Pump Replacement 1990
Order for Supplies or Services for Rebuild Irrigation Pump 1989
Structures West of the Tracks HS86 and HS87 1990
Proposed Project Cyclic Program for Rehab Work on West Irrigation 1993
Proposed Project Cyclic Program for Installation of New Surge Protection on Pump House 1994

Requests for Irrigation Service for HS87 1993-1994
Requisition for Water Pump Safety Hazard 1994
Order for Supplies or Services to Upgrade Water Pump Service According to Specifications in RFQ 1586-4-0002 1994
National Historic House Specifications 2005

Series 088 *PROJECTS RELATED TO HS88 PUMP HOUSE, 2000-2005*

Folder 001. HS88 [Documentation of Projects for HS88 2000-2005], 2000-2005

This folder contains:

Correspondence
PMIS Form for Reroof Five Historic Buildings 2001
PMIS Form for Repaint Exterior of Five Historic Buildings, Provide for Lead Reduction 2001
National Historic House Specifications 2005

Folder 002. HS88 [Duplicate Photographs and Photograph Logs], 2005

This folder contains:

Restoration of Doors on HS88 2005 Duplicate Photographs

Series 089 *PROJECTS RELATED TO HS89 CLARK FORK RIVER BRIDGE, 1976-2008*

Folder 001. HS89 [Clark Fork River Bridge Inspection Reports 1980-2003], 1980-2003

This folder contains:

Bridge Safety Inspection Report September 29, 1980
Bridge Safety Inspection Report August 12, 1982
Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges December 1988
Repair/Rehab Project Type 40 Rehabilitation of HS89 Clark Fork River Bridge
Correspondence from Jeffrey M. Berg, Structural Engineer, Regarding Inspection Reports 1996
Structure Inspection Report September 27, 1995
Field Notes Regarding Inspections of the Clark Fork River Bridge
Structure Inspection Report September 19, 1993
Bridge Inspection Report August 10, 1987
Bridge Safety Inspection Report August 8, 1985
Completion Report Repair Bridge Approach PX 1230-6-0049 1996
Structure Inspection Report August 5, 1997
Bridge Inspection Report September 9, 2003
Bridge Inspection Report September 19, 2001
Bridge Inspection Report September 22, 2007

Folder 002. HS89 [Clark Fork River Bridge Repair River Bridge Approach Contract 1996], 1996-2003

This folder contains:

Daily Diaries September-November 1996
Modification No. 2 Purchase Order No. PX-1230-6-0049 Repair Bridge Approach 1996
Modification No. 3 Purchase Order No. PX-1230-6-0049 Repair Bridge Approach 1996
Unit Price Contracts for Contractor Mastodon Sand & Gravel CO. 1996
Invoice for Mastodon Sand & Gravel CO. 1996
Correspondence Regarding Final Acceptance of Contract 1996
Time Line for the Completion of the Project 1996
Inspection Report for the Clark Fork River Bridge 2003

Folder 003. HS89 [Clark Fork River Bridge Repair River Bridge Approach 1996], 1996

This folder contains:

Damage Assessment Information
Joint Field Letter of Agreement
Submittal Package Contractor List
Permits Amendments and Modifications
Designation of Contracting Officer's Representative
Correspondence
Purchase Order
Time Extensions
Contract Specifications
Receipt of Offers for Repair Bridge Approach August 1, 1996

Folder 004. HS89 [Documentation of Projects for HS89 1976-2008], 1976-2008

This folder contains:

Work Request Logs106 Statement for Repair Clark Fork River Bridge 1976
Bridge Maintenance Report 1981
Summary of Deficiencies for Clark Fork River Bridge 1980
National Park Service Maintenance Division Bridge, Tunnel, Culvert Inventory 1982
Completion Report for Redeck Three Bridges 1982
Bridge Inspection Report July 24, 1991
Correspondence
Damage Assessment Form for Repair Bridge Approach Fills 1996
Damage Assessment Form for Approach Roads at Bridge Repair 1996
ERFO Program Approval Letter No. 3 for February 1996
Disaster Synthetic Industries Materials List
Maintenance Inspection Forms 1982-1986
Maintain River Corridor Bridges HS89 and HS90 2008
National Historic House Specifications 2005

PMIS Form for Repair Three Historic Bridges 2004
Stream Preservation Act Permit Application
Specifications for Bridges HS55, HS89, HS90
Loan Agreement Between USDA, Forest Service, Region 1, and the National
Park Service for use of Forest Service Equipment 2006
Architectural Drawings of Clark Fork River Bridge
Scope of Work for Engineering Design, Specifications, and Construction to
Correct Structural Deficiencies on Bridges
A Geotechnical Evaluation Report Prepared for the National Park Service;
Proposed Bridge Improvements January 24, 2005

Folder 005. HS89 [Oversize Archive Separation Sheets], 6/25/2009

This folder contains:

Archives and Manuscript Collections Separation Sheet for HS89 and HS90
Clark Fork and Slough Bridges Construction Drawings 2005

Series 090 *PROJECTS RELATED TO HS90 SLEW BRIDGE, 1980-2008*

Folder 001. HS90 [Slew Bridge Inspection Reports 1980-2007], 1980-2007

This folder contains:

Bridge Inspection Report August 22, 2007
Bridge Inspection Report August 18, 2005
Bridge Inspection Report September 9, 2003
Bridge Inspection Report September 19, 2001
Structure Inspection Report August 5, 1997
Structure Inspection Report September 27, 1995
Structure Inspection Report September 19, 1993
Bridge Inspection Report August 10, 1987
Bridge Safety Inspection Report August 8, 1985
Bridge Safety Inspection Report August 12, 1984
Bridge Safety Inspection Report September 29, 1980

Box 4

Folder 002. HS90 [Documentation of Projects for HS90 1980-2008], 1980-2008

This folder contains:

Work Request Logs
Bridge Maintenance Report 1981
Summary of Deficiencies For Slew Bridge 1980
Completion Report for Redeck Three Bridges 1982
National Park Service Bridge Inspection Report September 24, 1991
Maintenance Inspection Forms 1982-1986
Maintain River Corridor Bridges HS89 River Bridge and HS90 Slough
Bridge 2008

National Park Service Maintenance Division Bridge, Tunnel, and Culvert
Inventory 1982
PMIS Form for Repair Three Historic Bridges 2004
National Historic House Specifications 2005

Series 091 *PROJECTS RELATED TO HS91 WEST SIDE DITCH SYSTEM, 2005*

Folder 001. HS91 [National Historic House Specifications 2005], 2005
This folder contains:
National Historic House Specifications 2005

Series 092 *PROJECTS RELATED TO HS92 KOHRS-MANNING DITCH SYSTEM, 2005*

Folder 001. HS92 [National Historic House Specifications 2005], 2005
This folder contains:
National Historic House Specifications 2005

Series 093 *PROJECTS RELATED TO HS93 WARREN DITCH SYSTEM, 2005*

Folder 001. HS93 [National Historic House Specifications 2005], 2005
This folder contains:
National Historic House Specifications 2005

Series 094 *SCOPE OF WORK RESTORATION OF HISTORIC STRUCTURES
REVISED RECOMMENDATIONS DRAFT COPY 1980, 1980*

**Folder 001. [Scope of Work Restoration of Historic Structures Revised
Recommendations Draft Copy 1980], 1980**
This folder contains:
Scope of Work Restoration of Historic Structures Draft Copy August 7,
1980: Revised Recommendations October 30, 1980

Series 095 *SCOPE OF WORK RESTORATION: HS3 THRU HS31, Unknown*

Folder 001. [Scope of Work Restoration: HS3 thru HS31], Unknown
This folder contains:
Scope of Work Restoration: HS3 thru HS31

Series 096 *WARREN RANCH AREA SPECIFICATIONS 1990, 1990*

Folder 001. [Warren Ranch Area Specifications 1990], 1990
This folder contains:
Warren Ranch Area: Water, Sewar, Natural Gas, Other 1990
Warren Ranch Area: Uses for Structures 1990

Warren Ranch Area: Existing Conditions
Maps of Warren Ranch Area Existing Conditions
List of Structures in the Warren Ranch Area
Map of the Structures in the Warren Ranch Area
Dimensions of the Structures in the Warren Ranch Area
Gross Square Footage (GSF) of Structures in the Warren Ranch Area

Series 097 *GENERAL HISTORIC STRUCTURE SPECIFICATIONS, 1980-1995*

Folder 001. [General Historic Structure Specifications], 1980-1995

This folder contains:

Legend: Historic Structure Building Numbers HS1-53
Current Use of Historic Structures List 1990
Cost to Construct Estimates for HS8-HS85 1995
Old Cost to Construct Estimates HS1-HS53
Additions to Historic Structures List 1988
Numbered Historic Structures List 1980
List of Numbered Structures on Historic Base Map

Series 098 *HISTORIC PRESERVATION MAINTENANCE GUIDES 1979, 1979*

Folder 001. [Historic Preservation Maintenance Guides 1979], 1979

This folder contains:

Historic Preservation Maintenance Guides for the Historic Structures
Submitted by James R. McDonald Architect 1979

Series 099 *GEOTECHNICAL INVESTIGATION AND EXPLORATORY BORINGS
REPORTS 1979, 1979*

**Folder 001. [Geotechnical Investigation and Exploratory Borings
Reports 1979], 1979**

This folder contains:

Correspondence related to the Soils Reports 1979
Exploratory Borings Proposed Water Service Line written by Chen and
Associates, Inc. 1979
Geotechnical Investigation written by Chen and Associates, Inc. 1979

Series 100 *PRESERVATION GUIDE TECHNICAL MANUAL MARCH 7, 1983, 1983*

Folder 001. [Preservation Guide Technical Manual March 7, 1983], 1983

This folder contains:

Preservation Guide: Technical Manual March 7, 1983

Series 101 *PRESERVATION GUIDE: INSTRUCTIONS AND FORMS, Unknown*

Folder 001. [Preservation Guide: Instructions and Forms], Unknown

This folder contains:

Preservation Guide: Instructions and Forms

Series 102 *DRAFT MAINTENANCE GUIDES JRM 78-19 JUNE 1, 1979 LOG STRUCTURES, 1979*

Folder 001. [Draft Maintenance Guides JRM 78-19 June1, 1979 Log Structures], 1979

This folder contains:

Maintenance Specifications Outline for Log Structures HS14, 16, 19

Series 103 *DRAFT MAINTENANCE GUIDES JRM 78-19 JUNE 1, 1979 FRAME BUILDINGS, 1979*

Folder 001. [Draft Maintenance Guides JRM 78-19 June 1, 1979 Frame Buildings], 1979

This folder contains:

Elements of Structures in Non-Maintenance State List HS2-HS31

Maintenance Specifications Outline for Frame Buildings HS2 (Eastend), 3, 4, 6, 8, 9, 17, 18, 21, 22, 30, 31

Series 104 *RANCH FENCING SYSTEM 1983-2009, 1983-2009*

Folder 001. [Ranch Fencing System 1983-2009], 1983-2009

This folder contains:

Work Request Logs

Completion Report for Repair and Replace Fencing 1989

Completion Report for Rehab Site Fencing 1990

Completion Report for Rehab Boundary Fencing 1992

Commitment Control Register for Rehab Boundary Fencing 1992

Completion Report for Repair Park Fencing System 1995

Response to Specific Concerns for Fencing Preservation Maintenance 1995

Assessment of Effect for Fencing Preservation Maintenance 1995

Architectural Drawings and Photograph Copies

Assessment of Effect Form for Compliance Project GRKO-3-95 1995

Some 1979 Notes from Con Warren per Lyndel 1994

Compliance Review Form for Grazing, Control Cross Fence 1998

Correspondence Related to Grazing, Control Cross Fence Project 1998

Roads and Trails Work Completed FY-97

Duties for Preparation of Irrigation System 1997

Fences List

Program Change Proposal for Establish Fiscal Year 1994

Cyclic Maintenance Program 1993

Commitment Control Register for Repair Park Fence System 1994
Commitment Control Register for Rehab Boundary Fencing 1992
Warren Area Feed Lot Fencing 2000
Fencing Materials List
Jackleg Fencing: Replace Faulty Jackleg Fence Sections 2009

Series 105 *RANCH FENCING SYSTEM DUPLICATE PHOTOGRAPHS, 1995-2005*

Folder 001. [Ranch Fencing System Duplicate Photographs], 1995-2005

This folder contains:

Gate Repair 1995 Duplicate Photographs
Temporary Wind Break Near Feed Lots 2000 Duplicate Photograph
Gate Repair on Gate Near HS59 Before Repair 2005 Duplicate Photograph

Series 106 *PARKING LOT PROJECTS 1983-2003, 1983-2003*

Folder 001. [Parking Lot Projects 1983-2003], 1983-2003

This folder contains:

Work Request Logs
Proposal from J&H Painting to Restripe Parking Lot Visitor Parking 1983
Job Order Request Repaint White Stripes and Arrows in VC Parking Lot 1983
Article "Tom Stuart Home Landmark of '80 Being Torn Down"
List of Project by Project Number for 1586p95280031 1996
Unit Price Contract for Crack Seal and Seal Coat Asphalt 1997
Order for Supplies or Services for Reseal Parking Lot 1997
Maintenance Inspection Form 1986
Architectural Drawings for Entrance Gate into the Parking Lot
Anaconda Vocational Skills Training Project Check Sheet 1992
Compliance Review Form for Repair Asphalt Entrance Road 2001
Compliance Review Form for Temporary Parking and Walking Surface 2003

Series 107 *SURFACE TREAT PARKING AREA CONTRACT #P1586010007 2001, 2001*

Folder 001. [Surface Treat Parking Area Contract #P1586010007 2001], 2001

This folder contains:

Order for Supplies or Services for T-Bar-S Enterprises Inc. 2001
Architectural Drawing of Parking Lot Layout 2001
Correspondence
PMIS Form for Repair Asphalt Entrance Road 2001
Advance Acquisition Plan for Repair Asphalt Entrance Road 2001
Project Cost Accounting Data Entry Sheet
Notice of Award to T-Bar-S Enterprises Inc. 2001
Unit Price Contract for Surface Treat Parking Lot 2001

Series 108 *ROAD INVENTORY AND NEEDS STUDY 1980, 1980*

Folder 001. [Road Inventory and Needs Study 1980], 1980

This folder contains:

Road Inventory and Needs Study for Grant-Kohrs Ranch National Historic Site

Series 109 *PARKING AREA, TRAIL, AND UTILITIES SPECIFICATIONS 1975, 1975*

Folder 001. [Parking Area, Trail, and Utilities Specifications 1975], 1975

This folder contains:

Grant-Kohrs Ranch National Historic Site Parking Area, Trail, and Utilities Specifications Project No. 1586-0582 May 27, 1975

Series 110 *COTTONWOOD CREEK TRAIL, 1995*

Folder 001. [Cottonwood Creek Trail], 1995

This folder contains:

Work Request Logs

Correspondence Related to Cottonwood Creek Trail Bank Stabilization 1995

Stream Preservation Act Permit Application for Cottonwood Creek Trail Stabilization 1995

Architectural Drawings of Cottonwood Creek Trail 1995

Cottonwood Creek Flooding Timeline 1995

Grant-Kohrs Ranch Cottonwood Creek Nature Trail Booklet

Series 111 *JOHNSON CREEK TRAIL, 1995*

Folder 001. [Johnson Creek Trail], 1995

This folder contains:

Correspondence Related to Johnson Creek Restoration 1995

Correspondence Related to Johnson Creek Temporary Water Weirs 1995

Series 112 *FLOODING/TRAIL UNDERPASS 1996, 1996*

Folder 001. [Flooding/Trail Underpass 1996], 1996

This folder contains:

Map of Events Occurring on February 8-9, 1996 Flooding of the Ranch

Series 113 *PHOTOGRAPH LOGS FOR NEGATIVES AND SLIDES, 1994-2005*

Folder 001. [Photograph Logs for Negatives and Slides], 1994-2005

This folder contains:

Photograph Negative and Slide Logs 1994-2005 Corresponding to Boxes Containing Negatives and Slides

Series 114 *PHOTOGRAPH INDEX CARDS, 2001-2004*

Folder 001. [Photograph Index Cards], 2001-2004

This folder contains:

Photograph Index Cards Relating to the Corresponding Year Negatives and Photographs 2001-2004

Series 115 *OVERSIZE ARCHITECTURAL DRAWINGS, 1967-2005 (bulk dates: 1973-1986)*

Folder 001. HS1 [Architectural Drawings], 1979-1983

This folder contains:

HS1 As Constructed Drawings 451/41006-A Sheets 1-33 of 33 Prepared by R.L. Stevens Renovation of Mechanical & Electrical Systems Date 6/83

HS1 Construction Drawings 451/41006 Sheets 1-32 of 32 Prepared by R.L. Stevens Renovation of Mechanical & Electrical Systems Date 6/83

HS1 Existing Conditions 451/28013 PKG No 113 Sheets 3, 9, 13-20, 40, 41, 44, 45, 47, 48 of 64 Designed by FCK May 1, 1980

HS1 Water Main & Connection 451/41004A Sheets 1-7 of 7 Prepared by Tweed 10/79

HS1 Working Drawings 451/28013A Sheets 9, 11-19, 22, 38-41, 43, 45-50 of 57 Revised October 30, 1981 Original Date 12/8/80

Folder 002. HS1 [Architectural Drawings with TIC Number 451/28013], 1980

This folder contains:

HS1 Existing Conditions 451/28013 Complete Set PCIP PKG No. 113 Sheets 1-61 of 64 Drawn by RAN Checked by KDP May 1, 1980

Blueprints
5 Copies of 451/28013 With Mike McWright's Handwritten Notes Feb 21, 1980

Blueprints (No Sheet Numbers on them)

15 Copies of 451/28013 in Mylar with One Containing Sheet Number 42 of 52, The rest don't have sheet numbers on them.

2 Copies of 451/28013, No Sheet numbers on them.

Folder 003. HS1 [Architectural Drawings Related to Projects for HS1], 1975-1984

This folder contains:

2 Copies of HS1 Bathroom Cabinet Sheet 1 of 1 Date October 1986 James R. McDonald Architects Blueprints

HS1 Bathroom Cabinet Sheet 1 of 1 Date October 1986 With Mike McWright's Handwritten Notes Feb 21, 1980 Blueprint

HS1 Window Cover Details Trans# 14 Date 11/25/83 451/41006 Renovation of Mechanical & Electrical Systems Blueprint

HS1 Southwest Porch Roof Post Drawing #1 of 1 Job No. 8349 Date 8/11/83 Blueprint

HS1 Stabilization of Conservatory 451/80009 Date June 30, 1978 Sheet 1 of 1 Prepared by RAB Blueprint 2 Copies
HS1 Room Schedule Feb 22, 1980 Sheet 25 Blueprint
HS1 Shop Drawings Heating System Mechanical Plan Sheet 1 of 1
451/41006 Renovation of Mechanical & Electrical System Date 12/1/1983 Architectural Drawing
HS1 Big Sky Fire Protection, Inc. Crawl Space & Attic Piping Sheet 1-2 of 2 Date 12/20/83 451/41006 Renovation of Mechanical & Electrical System Blueprint with Handwritten Notes 2 Copies
HS1 First Security System/Fire Detection Intrusion Date 3/24/84 451/41006 Renovation of Mechanical & Electrical System Blueprint
HS1 Existing Conditions 1975 First & Second Floors Mylar 2 Copies
HS1 Architectural Drawing of Second Floor
HS1 South View of Outside of Ranch House Drawn by Lester Architectural Drawing
HS1 Second Floor Existing Conditions 1975 Date 3/1/77 Designed by Snell Drawn by Jarrett Checked by Snell Architectural Drawing
HS1 Second Floor HABS Drawing with Handwritten Notes 1976 & First Floor Architectural Drawings
HS1 Room 113 Architectural Drawing of Wall
HS1 2 Copies of Shop Drawing of Heating System 451/41006 Date 1/24/84 Blueprint
HS1 Plan Office Room #102 Plaster Stabilization Sheets 1-4 of 4 James R. McDonald Architects Blueprint
HS1 Garden Architectural Drawing
HS1 Bathroom Architectural Drawing
HS1 Fire/Intrusion Alarm Details 451/41006 Sheet 32 of 32 Date 6/83
Newspaper Montana Standard "On with the Steel" 5/11/99 Roofing Project

Folder 004. HS2 [Architectural Drawings], 1975-1980

This folder contains:

HS2 Existing Conditions Building Sections 451/28014 Date 12/79 Blueprints
HS2 Room Schedule Date 2/80 Blueprint
Snell Drawing of Bunkhouse Row Elevation BLDG No. 2 Blueprint
Existing Conditions Plan 1975 Date 3/77 Mylar
Existing Conditions Building Section Woodshed Rm1 1-Buggy Shed RM1
451/28014 Brown Mylar
Existing Conditions Building Sections (Separate Sections of Rooms)
451/28014 Brown Mylar
Existing Conditions Partial Floor Plan/Loft Plan 451/28014 Mylar 2 Copies
Existing Conditions South/East Partial Elevation 451/28014 Mylar

Folder 005. [Architectural Drawings], Unknown

This folder contains:

2 Architectural Drawings of Overhead Views of the Ranch

Folder 006. [Architectural Drawings], 1973-1986

This folder contains:

Copy of GRKO 15666 (HS58 CAB 3C Box22) Also copy in CKW Papers Series19 Subseries A Folder3 CAB3B

Survey of Sorenson & Co. Date 10/73 #2345ES Mylar and Paper Copy

Survey of Sunage Lagoon (Lars/Mary Annosr) 1983

Survey of Milwaukee Railroad Parcel and City Park done by Ray Masters
Date 6/1986

2 Copies of Boundary Map 451/80013A Date 10/84

Grant-Kohrs Historical Map by Frank Wastfall Date 2/15/1973

Folder 007. [Architectural Drawings], 1972-1997

This folder contains:

Surface Treat Parking Lot 451/80043 Sheets 1-2 of 2 Dates 3/5/97 and 2/97

The Lo-Lift Pump Co. HS87 Job # 84-7030-18 Date 11/14/84

Aerial Photograph of Deer Lodge Date 8/17/72

Folder 008. [Architectural Drawings], 1978-2000

This folder contains:

HS15 Thoroughbred Barn Structure Stabilization; Moving Plan & Details
Date 8/26/88 Page 1 & 2 Blueprint

HS45 and HS46 Typical Construction Mylar Handdrawn

HS58 Con Warren House Electrical Plan Date 10/27/95 Sheet 1 of 1

HS23 Metal Grainary Plan, Southwest Elevation Section A-A James R
McDonald Architect Date 10/1/79

HS18 Studs Out Grainary Plan, West/South Elevation, Section A-A James R
McDonald Architect Date 10/1/79

HS17 Buggy Shed Plan, South/East Elevation, Section A-A James R
McDonald Architect Date 10/1/79

HS9 1932 Dairy Plan East/West/North/South Elevation James R McDonald
Architect Date 10/1/79

HS6 1935 Grainary Plan West/South/East Elevation Section A-A James R
McDonald Architect Date 10/1/79

HS4 Coal Shed Plan Southeast/Southwest Elevation Section A-A James R
McDonald Architect Date 10/1/79

Overhead Boundary Lines of Grant-Kohrs Architectural Drawing

HS30 Stabilization of Double Stallion Barn 451/80008 Sheet 1-2 of 2 Date
5/25/78

HS3 Stabilization of Double Stallion Barn Date March 7, 1980 Regional
Historic Preservation Team Rocky Mountain Region

Clark Fork & Slough Bridge Repairs Date 2005 451/25002 Architectural
Drawings

HS59 Door Repair Architectural Drawings

HS59 North Wall Room 1 Dimensions Architectural Drawing

HS59 Door Panels for Chicken Coop Architectural Drawing 2 Copies

HS59 Chicken Coop Palace Dimensions Architectural Drawing

HS59 Chicken Coop Door South Side Architectural Drawing
HS8 Privy Article "Rural Nevadans retain fondness for privies: WPA's Fly-
Proof Privy Program dotted rural areas with new outhouses" Montana
Standard Sunday March 5, 2000

Folder 009. [Architectural Drawings], 1975-1980

This folder contains:

Bridge 451/80003 Sheet 2-3 of 3 Date 5/26/76
Blank Room Schedule Feb 20, 1980 Sheet 7 of (blank)
HS6 Foundation Stabilization 451/80011 Sheet 1 of 1 Date 2/12/79 3 Total
Copies (1 copy has handwritten notes)
Asphalt Composition Roofing Hex Pattern 1933-1934 Sheet 1 of 1 Date
1/10/77
HS15 Copy of Elevations
HS15 Thoroughbred Barn Existing Conditions 1975 Longitudinal Section B-
B, South Elevation, Transverse Section A-A, North Elevation
HS15 Thoroughbred Barn Existing Conditions 1975 East/West Elevations
Proposed Scenic Easement Areas GRKO Ranch National Historic
Architectural Drawing
Aerial Drawing of GRKO

Folder 010. [Architectural Drawings], 1974

This folder contains:

3 Copies of Aerial View of GRKO from the East, Existing Conditions-
Location within the Park 1974 451/(blank) Sheet 1 Mylar
2 Copies of Existing Conditions HS7 Drafthouse Barn Loft Floor Plan and
Floor Plan 451/28015 Mylar

Folder 011. [Architectural Drawings], 1967-1987

This folder contains:

Existing Land Ownership 20,002B Date 10/72
Boundary Map GRKO 451/80013B Date 9/87
Boundary Map GRKO 451/80000C Date 5/74 Sheet 1 of 1
Land Acquisition 451/80014 Date 5/80
3 Copies of Historical Base Map Proposed Site 1862-1971
2 Copies of Enlarged Sections of Historical Base Map Proposed Site 1862-
1971 Buildings and Corrals Topographic
Set of Contour Maps with Perspective Plots from Different Views
Archaeological Base Map GRKO Date 4/82 Deer Lodge Quadrangle
Topographic
Archaeological Conley Lake Quadrangle 1967 Topographic

Folder 012. [Architectural Drawings], 1977-1987

This folder contains:

Special Notes and Requirements Applying to GRKO Ranch Property Old Milwaukee Railroad Sheet 4-6 of 18 Job No. 2145054 Architectural Drawing
Boundary Map 451/80013A Date Oct 84 Mylar
Boundary Map 451/80013B Date Sept 87 Architectural Drawing with Handwritten Notes 2 Copies
GRKO Ranch Physiographic Map colored with crayon to show the land architecture Mylar
GRKO Ranch Physiographic Map Blueprint
Weed Locations on Ranch: Spotted Knapweed, Whitetop, Field Bindweed, Russian Knapweed and Musk Thistle, Leafy Spurge, Field Plot Sites, and Canada Thistle
Historical Base Map Key to Structures
Site Plan restoration Proposal Date 3/1/77 Handwritten Notes by Meikle/McWright HS15 1980's Historic Lore
Site Plan Restoration Proposal Date 3/1/77
*These materials apart of Natural Resources when they were a section of Facility Management

Folder 013. [Architectural Drawings], 1984

This folder contains:

Topographic Map of Grant-Kohrs Ranch

Curatorial Cleaning Schedule of HS1, 2, 3, 5, 13 Pages 1-4 Feb 29, 1984

*Series 116 FACILITY MANAGEMENT HISTORIC STRUCTURE PROJECT
NEGATIVES AND SLIDES, 1978-2005 (bulk dates: 1978-2005)*

Box 1

Folder 001. [Negatives], 1978-1993

This box contains:

Negatives (80 Pages) related to projects for Facility Management Division 1978-1993.

Box 2

Folder 002. [Negatives], 1994-1999

This box contains:

Negatives (80 Pages) related to projects for Facility Management Division 1994-1999.

Box 3

Folder 003. [Negatives], 1999-2005

This box contains:

Negatives (80 Pages) for projects related to Facility Management Records 1999-2005.

Box 4**Folder 004. [Negatives and Slides], 1995**

This box contains:

Negatives and slides (30 Pages) related to projects for Facility Management Division 1995.

Box 5**Folder 005. [Slides], 1995-2004**

This box contains:

Slides (22 Pages) related to projects for Facility Management Division 1995-2004.

Series 117 COMPACT DISKS OF PHOTOGRAPHS AND FLOPPY DISKS, 2001-2005 (bulk dates: 2001-2005)

Box 1

Compact Disks of Photographs and Floppy Disks, 2001-2005